

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R 41W

H-9

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Quarter Corner common to Sections 22 & 27, T48N R41W.

I, Earl W. Applekamp, in a field survey on May 9, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wills Burt, U.S. Deputy Surveyor,
May 1851. Set Wood Post.

ORIGINAL BEARING TREES:

White Pine 34" S50°W 7.26 feet
Maple 6" S64°E 11.22 feet

PEER GROUP APPROVED
Earl W. Applekamp
COUNTY REPRESENTATIVE
5-12-97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. I found a 1/2" Iron Pin 3 feet above the ground, 33 feet North of the blacktop road. A yellow location tag was on a wood stake. the tag identified the location and was placed by Champion Timberlands. No evidence was found in the road. I set the corner in the center-line of the blacktop road and equal distance between opposite section corners East & West.

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x24" Rebar with a 3" stamped aluminum cap 2" below top of blacktop in the center-line of the road. I established a Reference Monument, a 2 1/2"x30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, 1/4, R.M., S22, S27, 1997, P.S. 17610. I also established 3 other witness objects as follows:

REF. MON. N02°W 41.30 feet - Power Pole S01°E 32.86 feet
3" Aspen N45°E 57.63 feet - NW Cor.House S39°W 124.45 feet



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date May 9, 1997