

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON

(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 41W

I-7

T R

T R

T R

T R

2. Property Controlling
In Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

REMONUMENTATION

OCT 3 0 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner common to Sections 14, 15, 22 & 23, T48N R41W.

I, Earl W. Applekamp, in a field survey on May 01, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wills Burt, U.S. Deputy Surveyor, June 1851. Set Post.

ORIGINAL BEARING TREES:

14" Spruce N42°E 23.10 feet
12" Maple S21°E 27.06 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position falls in a county gravel road which has been in existence since the early 1900's. An old fence line runs East from the apparent corner position. The fence line separates a woods to the North and a field South, using the intersection of the fence line and center-line of road is in agreement with the original field note calls. I re-established the corner at this position.

Research on file with the County Remonumentation Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE

5-12-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"X24" rebar with a 3" stamped cap in center-line, 6" below top of the gravel road. I set a reference monument, a 2 1/2"X30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, R.M., S14, S15, S22, S23, 1997, P.S. 17610. I established 3 other witness objects.

REF. MON. S42°W 52.06' - 7" Aspen N37°E 104.11'
5" Aspen N55°-30'W 65.81' - Power Pole N84°E 30.60'



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date May 2, 1997