

SURVEY & REMONUMENTATION

APR 25 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

- | | | |
|---------------------------------------|-------------------------|---------|
| 1. Public Land Survey | T <u>48</u> R <u>43</u> | K - 5.3 |
| | T _____ R _____ | |
| | T _____ R _____ | |
| | T _____ R _____ | |
| 2. Property Controlling
in Section | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |
| 3. Miscellaneous
Property in Sec. | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |

Recorded December 5 1994
at 2:05 o'clock P. M. in
Liber 3 page 227
Julia M. Arley Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Meander Corner Section 12 & 13, T48N R43W

I, Earl W. Applekamp, in a field survey on November 05, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, U.S. Deputy Surveyor, Sept. 8, 1845.

Original bearing trees:

8" Cedar Post

Cedar 12" N88°W 39 Links (25.74)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On July 30, 1973 a 2½" pipe was found marking the meander corner. This pipe was used for several surveys in the area. This 2½" pipe and the NW Corner of Section 13 is along the centerline of a county road which has been in existence for 60 plus years. The distance from the NW Corner of Section 13 to the 2½" pipe is in agreement with the call on the original field notes surveyed in 1848.

Research on file with County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2¼" x 30" long split base aluminum pipe with a 3¼" cap stamped to read: County Remonumentation, M.C. S12, S13, T48N R43W, 1994 P.S. 17610. The following trees and objects were used to tie in the corner.

11" Maple	N36°W	43.04'	-	9" Ash	S70°E	14.16'
5" Ash	S56°W	24.14'	-	Steel sign post	East	0.73'

**ONTONAGON COUNTY
PEER APPROVED**

EW Applekamp
Ont Co Rep
11-30-94



Signed by Earl W. Applekamp

Date

November 25, 1994

Surveyor's Michigan License No. 17610