BUHVEY & REMONUMENTATION

APR 2 9 1996

JUDITH D. ROEHM

07/19/95

Ontonason County 10

9.00

Fee 3/ 283 JEM

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Page 1

For corners in

	Ontonagon (County)	Located In:	Corner Code ##
1.	Public Land Survey	T50N R 42 W	F-13
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	

_ T __

Register of Deeds Stamp & File Number

4. Lot No. ___ , Recorded Plat .


5. Private Claims _

Property in Sec.

Quarter Corner 33 and 4; T.49-50 N., R.42 W.

__ R __

L Richard L. Drahn in a field survey on June 8, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: Corner established by William Burt on August 18, 1847. Original BTs --- 9 Sugar N.30 E., 11 links (7.26') --- 5" Lynn N.42 W., 11 links (7.26') ---. Original BTs --- 9"

Corner recovered by Richard L. Drahn, RLS 21564 from the remains of the two original bearing trees and retracement distances to recovered section corners east and west. He set a 2" x 5' iron pipe monument with a 3" brass cap stamped to identify the corner and established the following new bearing (1995 conditions in parenthesis)

10" (12") N. Red Oak N.43 E. (N.45 E.)

32.3 ft. (32.43')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6" (6") 10" (14")

Sugar Maple

S.25 E. (S.22 E.)

44.5 ft. (44.24') 67.1 ft. (67.15')

N. Red Oak

S.51 W. (S.55 W.)

Steel rail

South (S.05 W.)

Corner monument recovered as described and in good condition.

Corner recorded in Liber 1, Page 156 of Ontonagon County Records on 4/25/79.

PEER GROOP APPROVED

Resource grade GPS Lat. 46-40.768 N

Long. 89-33.840 W


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the above described monument I blazed and scribed the following:

4"

Sugar Maple

N.35 W.

22.85 feet



Richard L. Drah

June 9, 1995

Surveyor's Michigan License No. _

21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

z - 11