

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon Located In: Corner Code #
1. Public Land Survey T 51N R 37W F3
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and a central dot at row 3, column F.

I, Stephan J. Szyszkoski, in a field survey on 08/20/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F3) Quarter corner common to Sections 4 and 9. In 1976, K.L.Sackett RLS reestablished the position for the corner midway and on line between Section corners E3 and G3. Set 1"IDx36" I.pipe with 4" aluminum cap. 6" Sugar N75°W 25.0'; 5" Sugar S23°E 14.4'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F3) Found the 1976 monument in good condition and at record bearing and distance from the 1976 NBTs: The Maple (rec. as Sugar) SE is in good condition with overgrown blazes; the Sugar NW is a stump. The position of the monument is substantially at the record position between Section corners and I accept same as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F3) Fd. 1"ID I.pipe with 4" alum. State of MI cap. Set measuring nail with MDNR tag in the side of: 10" Maple S17°E 14.7' overgrown blazes (1976 NBT) 4" Sugar N82°W 12.85' mrkd "1/4S NBT" 6" Y.Birch N32°W 12.9' do 7" Y.Birch N05°W 6.5' do Set sq'd cedar post adjacent. E= 7846986.821 N= 230213.707



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by [Signature] Date 08/26/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division