

SURVEY & REMONUMENTATION

APR 25 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

R B
104.62
Gla
SE

COMMISSION

For corners in

ONTONAGON

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 52 R 38
T 52 R 39

M-1.8

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Recorded October 19 1994
at 2:13 clock P.M.
Liber 3 page 213
Julie Mackay
Register of Deeds

Register of Deeds Stamp & File Number

M.C. Sections 1, 6, T52N R38W R39W

Earl W. Applekamp

I, _____, in a field survey on September 15, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Wood Post

Fir 10"

S04°W

25 Links (16.50')

ONTONAGON COUNTY
PEER APPROVED

Earl W Applekamp
Ontonagon Co. Rep.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. The meander corner was set on a line with the East 1/4 Corner and the NE Corner of the Section. A sketch of the location is shown on the back of this form. The position is marked with a permanent monument described below.

Research on file with County Remonumentation Representative



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2"x30" split aluminum pipe with a 3 1/4" cap, stamped to read: County Remonumentation M.C. S-1, S-6, 1994 P.S. 17610 The corner is tied to the following trees and objects.

White Ash 5"
White Ash 5"

N80°W
S19°W

36.35'
47.00'

Black Ash 7"
Steel Sign Post East

N61°E

13.49'
1.42'

Signed by

Earl W Applekamp

Date

October 07, 1994

Surveyor's Michigan License No.

17610

