

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

(County)

Located In

Corner Code #

1. Public Land Survey

T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S 23 T 33N R 2E 13  
S 23 T 33N R 2E 16

3. Miscellaneous  
Property in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on June 09, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

13- This corner position was not established during the original government survey.

16- Marcus Schaaf R.L.S. #3104 index shows he set a monument for the corner while working in the area CIRCA 1940.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

13- Established the Northwest corner of the Southeast quarter of the Southeast quarter of section 23 as per B.L.M. instructions for the subdivision of a section.

16- Found a 2" Pipe added 1/2" x 18" rod with PS Cap #33981

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13- Set a 5/8" X 32" iron rod with PS Cap #33981

Wit: Set a nail and tag in Southwest side of a 14" Red Pine N41°W 50.32'

Set a nail and tag in Southeast side of a 12" Red Pine N66°E 36.92'

Set a nail and tag in the Northeast side of a 10" Jack Pine S23°E 6.95'

Set a nail and tag in the North side of a 10" Jack Pine S31°W 15.20'

Carsonite Post North 1'±

16- Set 1/2" X 18" iron rod with PS cap #33981 in found 2" pipe

Wit: Set nail and tag in Northwest side of a 13" Oak N33°E 27.91'

Set nail and tag in Southwest side of a 10" Oak S35°E 21.10'

Set nail and tag in the Southeast side of a 13" Oak S58°W 39.49'

Set nail and tag in the Southwest side of a 14" Oak N53°W 58.73'

Carsonite post North 1'±

Signed by:

Carl T. Kiiskila

Date:

9-15-08

Surveyor's Michigan License No.:

33981

