

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

(County)

Located In

Corner Code #

1. Public Land Survey

T 33N R 2E G-11

T

2. Property

Controlling in

Section

S T R

S

3. Miscellaneous

Property in Section

S T R

S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 18, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-11 G.L.O. G.H. Cannon, 1851, Set post for corner common to sections 27,28,33 and 34.

Wit: Spruce Pine 6" N25°E 32 links

Spruce Pine 8" S48°W 26 links

Michigan Department of Conservation surveyor Marcus Schaaf R.L.S. #3104 sunk iron for corner while surveying in the area circa 1940. No witnesses or type of monument given.

Delmer E. Porter L.S. #15410 1986 Set ½" rod and cap #15410 using Marcus Schaaf survey information.

Wit: 5" W. Pine S41°W 78.55'

4" Oak N56°W 13.35'

5" J. Pine N23°W 60.40'

Ctr Well Pump N37°E 78.10'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

G-11 Re-established the section corner to sections 27,28,33 & 34 from Delmer E. Porter L.S. #15410 witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 Set a 5/8" re-rod with P.S. Cap #33981

Wit: ½" rod with cap N3°W 8.61'

8" J. Pine N19°W 60.42'

Ctr Well Pump N40°E 78.05'

8" R. Pine N43°W 78.45'

8" Oak S20°E 38.45'

The pin falls in the Ctr East-West road

Note: The ½" rod with cap is a traverse point set by Summit Surveying.



Signed by:

Carl T. Kiiskila

Date:

8-20-07

Surveyor's Michigan License No.:

33981