

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Presque Isle
(County)

Located In

Corner Code #

1. Public Land Survey	T	33N	R	4E	E-12
	T	33N	R	4E	E-13
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 30, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-13 G.L.O. John Hodgson D.S. 1840
Set post corner section 32 and 33 in Swamp
Wit: Tamarack 6 N23°E 8 Links
Balsam 6 N60°W 10 links

E-12 G.L.O. Alfred Millerd D.S. 1855
Set quarter section post
Wit: Yellow Pine 14 S30°W 41 links
White Pine 14 N50°E 32 links

Page 628, Presque Isle County Land Corner Records April 1983. While working for Porter Surveys, Ronald R. Bischer L.S. #22428 found 4X4 stake and one O.B.T. stub, possible set by Frank Smith, set 1/2" rod.
Wit: S87°E 24.54' 8" Cedar, S14°E 21.33' 6" Cedar, S25°W 25.28' 10" Cedar

Donald E. Marlatt L.S. #18660 set this corner by single proportionate measure while doing a survey in section 33. In 1993 no witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-13 Found 1/2" rod.

E-12 Found 1/2" capped rod #18660 Marlatt.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13 Found 1/2" rod set DNR monument
Wit: 8" Twin Cedar S82°E 24.72'
10" Cedar South 19.26'
12" Cedar S46°W 37.13'
20" White Pine N70°W 36.99'
Carsonite Post North 1'±
Corner falls in E-W Fence line

E-12 Found 1/2" capped rod with cap #18660 Marlatt
Set DNR monument
Wit: 6" White Pine S05°W 101.28'
*10" White Pine N71°E 37.47'
*16" Red Pine N30°E 109.61'
14" White Pine N13°E 87.28'
Carsonite Post North 1'±

* Old witnesses by others

Signed by:

Carl T. Kiiskila

Date:

8-26-02

Surveyor's Michigan License No.:

33981

