

1996 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle
(County)

Located In:

Corner Code #

1. Public Land Survey

T34NR5E

C-1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

PRESQUE ISLE COUNTY
RECORDED

96 JUN -4 AM 11:26

Jana M. Samt
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Norman J. Quaine in a field survey on Dec. 8, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-1 1840
Twp. lines run
by John Hodgson
Deputy Surveyor
Set Post Cor of Sec.
31&32, T35N, R5E
Balsam 8 N43W 36
Hemlock 4 N49E 11

1856
Examination of
Twp line by
Alfred Millerd
Deputy Surveyor
Notes indicate he fd
Hodgson's cor. Wit from
tie in from S. Are
Y Birch 10 S65W 39
Sugar 8 S12E 24

May 5, 1948

Survey by Donald A. Marlatt - R.S.
Scott & Assoc. (not recorded)
No physical Description available
for cor on face of document

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1
December 8, 1995
Norman J. Quaine
P.S.#33984, Porter's
Survey P.C.
1996 P.I. Co. State
Remonumentation

Fd 1/2" Rod & Cap #15410
in Mon Box
Mon Box top is unremovable
Hole was chiseled thru cap
when found
S50°W 46.64' P. Pole

1970

Wit. from Scott & Assoc.
(Not recorded) Obtained by
Porter's Survey from Scotts
P.K. Nail (Scott 1970)
S10°E 58.20' 6" Balsam
S45°W 46.59' P. Pole

Sept. 29, 1978
LCRC, Delmer E. Porter
LS#15410
Replaced P.K. Nail w/ 1/2"
Rd & Cap #15410 & put in
Mon Box
N36°W 54.61' Tele Cable
Box(Gone)
S08°E 78.38' 5" Apple(Gone)
S50°W 46.66' P. Pole

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1
Left 1/2" Rod & Cap #15410
In Mon Box
S50°W 46.64' P. Pole
S31°E 55.17' 5" Cedar
S06°E 52.39' 3" Cedar
S28°W 51.77' 4" Balsam
Int. Heythaler & Klee Rd.

Ratified by Peer Group
in accordance with P.A. 345

Chairman Delmer E. PorterDate 5/22/96

*Witness tags & nails.

Porter's Survey P.C.
Signed by Norman J. Quaine

Date May 29, 1996Surveyor's Michigan License No. 33984