

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

2000 OCT 30 PM 3:28

For corners in 2000 PRESQUE ISLE COUNTY, STATE OF MICHIGAN
REMONUMENTATION

Presque Isle

(County)

Located In:

Corner Code #

Janet M. Lamb
REGISTER OF DEEDSSURVEY &
REMONUMENTATION

FEB 12 2001

Register of Deeds Stamp & File Number

1. Public Land Survey

T 35N R 2E

G-12

T 35N R 2E

H-11

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Delmer E. Porter, in a field survey on 09/5/00, 19__ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-12
1/2" ROD BY CEDAR STAKE
S 20° W 82.38' 15" ASH
S 77° W 9.65' 4" ASPEN
N 17° E 6.68' 5" ASPEN
S 66° E 9.00' 8" ASPEN

H-11
1" PIPE
N 71° E 53.13' 12" MAPLE
S 35° E 102.37' P. POLE
SOUTH 3.0' RD C/L

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-12
FOUND 1/2" ROD
S 20° W 82.38' 15" ASH (OW)
S 77° W 9.65' 6" ASPEN (OW)
N 17° E 6.68' 7" ASPEN (OW)
S 66° E 9.00' 9" ASPEN (OW)



H-11
FOUND 1" PIPE
NO WITNESSES

Ratified by Peer Group
in accordance with P.A. 345

Chairman *Norman J. Chas*Date 10/27/00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12
1/2" ROD
S 20° W 82.38' 15" ASH
S 77° W 9.65' 6" ASPEN
N 17° E 6.68' 7" ASPEN
S 66° E 9.00' 9" ASPEN

H-11
1" PIPE
S 54° W 38.38' 10" BOX ELDER
N 15° W 44.37' 14" MAPLE
N 73° E 43.40' 19" BAM
S 33° W 28.30' 7" APPLE

*WITNESS TAGS & NAILS USED.

Signed by *Delmer E. Porter*Surveyor's Michigan License No. 15410Date 10/4/00