

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

Located In

Corner Code #

(County)

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 20	T 36N	R 2E	11
	S 20	T 36N	R 2E	16
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on August 5, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

11 – SW 1/16 Corner, Section 20, T36N, R2E

16 – E 1/16 Corner, common to sec.'s 20 & 29, T36N, R2E

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

11 – SW 1/16 Corner, Section 20, T36N, R2E

16 – E 1/16 Corner, common to sec.'s 20 & 29, T36N, R2E

Set stamped 2" dia. Alum. cap on 5/8"x34" rebar per standard BLM procedure. Found 9" dia. Y.Pine snag 10' tall with very evident hatchet marks on SW side facing where corner position falls, 2.5' away. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. Alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11 – SW 1/16 Corner, Section 20, T36N, R2E

16 – E 1/16 Corner, common to sec.'s 20 & 29, T36N, R2E

Stamped 2" dia. Alum. cap on 5/8"x34" rebar.

Stamped 2" dia. Alum. cap on 5/8"x34" rebar.

Wit: N20°E 52.96' to set N&T on E side 16" R.Oak  
N75°E 2.58' to set N&T on S side 9" Dead Y.Pine snag (snag had very evident hatchet marks on SW side)  
S43°E 14.55' to set N&T on SW side 18" R. Pine  
S03°W 40.81' to N&T on E side 17" R.Oak  
N63°W 27.03' to set N&T on S side 6" R.Maple  
Set Blue Carsonite Post w/ location tag 1' North

Wit: N30°E 42.85' to set N&T on W side 18" R.Pine  
S14°E 50.41' to set N&T on NE side 13" R. Pine  
S66°W 23.74' to set N&T on S side 5" R.Maple  
N51°W 35.42' to set N&T on S side 21" R.Pine  
Set Blue Carsonite Post w/ location tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

10-8-09

