ROSCOMMON COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF EXTREMEMON

LAND CORNER RECORDATION CERTIFICATE **可以外的总统的**

9 19 4 193 Dec 16

المعالم المعارض المنازي	Filing Requ	Filing Requirement of Act 74, Mich. P.A. 1970					
or corners in			Porte				
Roscommon	Located In:	Corner Code ##	•				
(County)			REG19				

NERS

10

11

12 13

(County)						REGIST									
1.	Public Land Survey	T T	T <u>21N</u> R <u>2W</u> T R T R T R		<u>K-9</u>		ROSCOMMON COUNTY PEER GROUP APPROVAL DATE 12-7-93								
2.	Property Controlling	S T	R				, DA	· <u>-</u> .		<u> </u>	<u> </u>		<u></u>	•	
	in Section	S T	R	· ·		TO BE	FILED	IN	LI	BER	3 ()F I	_AND	CO	R
3.	Miscellaneous	S T	R			1	gister o								
	Property in Sec.	s T	R												
4.	Lot No,	Recorded Plat					- а	B (: D	E F	G	н	ı J	к	L
5.	Private Claims	<u> </u>					[П		ТТ		\top		Т	Т
		•					2	6-	— <u>5</u> —	+-	+	- 3	十²·	_	-1 - l
							3 —	┨		+ +		+-	+		┿
							4	}	8-	┯∮	+	-10-	1-1	+	-12
I, _	Larry L. Cavanagh	_ , in a field survey	on Nove	mber	, 19 <u>93</u>		5	11			_	┷	$\downarrow \downarrow$	+	+
	hereby certify that under re						6	 <mark>8</mark>	 17-	+-!	- 	-1 ₅	14		- - 3

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration:

W/post placed by Wm A. Burt 1850 Beech 14" S63°E 27 Beech 12" N42°W 49

1990 Land corner recordation L-1,P-282 %"x18" capped steel bar, L. Cavanagh N24°E 12" Maple 17.55
N73°W 3" Poplar 11.15
S21°W 3" Poplar 16.95

\$52°E 4" Poplar 9.95

Fence line 20' East

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" capped iron

NE & SE witnesses also found (1990)

New fence constructed N-S direction 4' West of this corner.

Accepted as the best available evidence of the position of the original corner.

See filed dossier for detail of report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Roscommon Co. Std. Mon stamped K-9 17614 N24°E Nail & tag in 12" Maple 18.0 N35°W Nail & tag in 4"x4" Fence post 7.65 \$17°W Nail & tag in 4"x4" Fence post 12.60 S52°E Nail & tag in 4" Poplar 10.04 Carsonite post North 1.20

1993

OF MICHIGAN LARRY L **CAVANAGH** PROFESSIONAL SURVEYOR No. 17614 AAOFESSION

Date

Surveyor's Michigan License No. _

December 7

17614

Peer Group Approved

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983