

DEC 16 9 20 AM '93

8949

FEB 18 1994

## ROSCOMMON COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Roscommon  
(County)

Located in:

Corner Code #

- |                                       |                         |     |
|---------------------------------------|-------------------------|-----|
| 1. Public Land Survey                 | T 21N, R 1W             | M-8 |
|                                       | T _____ R _____         |     |
|                                       | T _____ R _____         |     |
|                                       | T _____ R _____         |     |
|                                       | T _____ R _____         |     |
| 2. Property Controlling<br>in Section | S _____ T _____ R _____ |     |
|                                       | S _____ T _____ R _____ |     |
| 3. Miscellaneous<br>Property in Sec.  | S _____ T _____ R _____ |     |
|                                       | S _____ T _____ R _____ |     |

ROSCOMMON COUNTY  
PEER GROUP APPROVAL

DATE 11-30-93

TO BE FILED IN LIBER 3 OF LAND CORNERS

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Larry L. Cavanagh, in a field survey on November, 1993,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

W/post placed by John Brink 1837	1990 Land Corner recordation
Hemlock 10" N37°W 23 Lks	1/2" Bolt in Pav't box
Birch 8" S47°W 33 Lks	N29°W SE Cor of Gas pump island 79.3
	S51°E Spike in 22" W. Pine 52.48
1947 Henning & Ostling survey	N37°E Spike in Utility pole 66.15
5/8"x24" bar	S31°W Spike in Utility pole 66.73
SE Cor Gas pump island N29°W 79.3	
W. Pine 6" S51°30'E 53.1	
Aspen 6" N50°30'E 95.0	
1968 Little Fawn Sub. L-6,P-24	
1975± Liber 2 corner record	
(Same as 1947)	

1993 Land corner record (Lapham)  
1" Sq Bolt  
N30°E 66.10 P. Pole  
N35°W 83.45 SE Cor of stone Hse  
S30°W 66.70 P. pole

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd 1/2" Bolt in Pav't Box  
1990 Wit: Pine Cut, Stump still there  
Gas pump island, gone  
All 1993 Witnesses

and is accepted as the best available evidence of the position of the original corner.

See filed dossier for detail of report.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Roscommon Co. Std. Mon in Pav't box stamped A-M-8 17614  
S22°E Nail & tag in 16" W. Pine 86.58  
S37°W Nail & tag in P. pole 66.63  
N35°E Nail & tag in P. Pole 66.10  
N41°W SE Cor of Stone Bldg 83.37



Signed by

Date

Surveyor's Michigan License No.

17614

Date November 30, 1993

Peer Group Approved

LIBER 3

PAGE 15