

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon
(County)

Located In

Corner Code #

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Section

4. Lot No: Recorded Plat:

5. Private Claims:

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on March 29 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

2 – E 1/16 Corner, comm. to sec.'s 22 & 27, T22N,R3W

5 – CN 1/16 Corner, Section 27, T22N,R3W

1962 – Survey Map – George D. Henning, P.S.#2240 – Set 1" x 36" pipe. 8" W. Oak S43°W 68.6' 4" J. Pine S28°E 51.2'

1962 – Survey Map – George D. Henning, P.S.#2240 Set 1/2" bar and post. 12" W. Oak S41°E 14.5' 5" Maple S73°W 31.0'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

2 – E 1/16 Corner, comm. to sec.'s 22 & 27, T22N,R3W

5 – CN 1/16 Corner, Section 27, T22N,R3W

Set stamped 2" dia. alum. cap on 5/8"x34" rebar in c/l E-W paved road. Henning's corner was obliterated due to previous road construction. Set corner by standard BLM procedure and fits one of Henning's witnesses within 0.08'. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. alum. cap on 5/8"x34" rebar per standard BLM procedure. Found 1/2" bar per Henning 1.23' North of corner position. Did not accept this position for the corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2 – E 1/16 Corner, comm. to sec.'s 22 & 27, T22N,R3W

5 – CN 1/16 Corner, Section 27, T22N,R3W

2" dia. Aluminum cap on 5/8"x34" rebar

2" dia. Aluminum cap on 5/8"x34" rebar

Wit: N10°E 52.83' to set N&T on E side 7" W. Pine S58°E 76.00' to set N&T on SW side 5" W. Pine *S29°E 51.31' to set N&T on SW side 9" J. Pine (51.12' to blaze) N26°W 66.97' to set N&T on SW side 12" Oak Set Blue Carsonite post w/location tag 33' South

Wit: N73°E 13.18' to set N&T on S side 5" B. Fir S19°E 14.35' to set N&T on E side 5" B. Fir S77°W 4.85' to set N&T on SE side 4" J. Pine N32°W 18.30' to set N&T on SE side 5" B. Fir North 1.23' to fd. 1/2" iron bar North 0.97' to 2" dia. x 4' tall pipe Set Blue Carsonite post w/location tag 1' North

* Previous recorded witness.

Surveyor's Michigan License No.: 33981



4-12-10