

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Roscommon

(County)

Located In

Corner Code #

1. Public Land Survey T 22N R 3W G-9
T R
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on March 30 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-9 – Section corner comm. to sec.'s 21,22,27&28, T22N,R3W

2005 – Remon L.C.R.C. – L.3, p.1049 – Marvin E. Myers, P.S.
#31600 – Set standard county monument in box after road construction.
6" Cedar N12°W 39.19'
6" Cedar N20°E 42.99'
10" Cedar N22°W 54.07'
8" Tamarack S21°E 44.86'
6" Cedar S35°W 39.56'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

G-9 – Section corner comm. to sec.'s 21,22,27&28, T22N,R3W

Found Roscommon County monument in monument box in centerline of E-W paved road per L.C.R.C., L.3, p.1049. One of the nails was missing on a witness; so reason for re-witnessing corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 – Section corner comm. to sec.'s 21,22,27&28, T22N,R3W

Standard Roscommon County monument in mon. box

Wit: *N13°E 42.99' to fd. N&T in 8" Cedar
*S34°E 44.90' to set N&T on NE side 9" Tamarack
*S24°W 39.60' to fd. N&T in 8" Cedar
*N33°W 54.05' to fd. N&T in 11" Cedar
*N20°W 39.15' to fd. N&T in 8" Cedar

* Previous recorded witness.

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981



4-12-10