

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Roscommon

Located In

Corner Code #

(County)

1. Public Land Survey T 22N R 3W H-10
T R

2. Property Controlling in Section S 27 T 22N R 3W 9
S T R

3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on March 18 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

H-10 - C 1/4 Corner, section 27, T22N,R3W

9 - CE 1/16 Corner, Section 27, T22N,R3W

1994 - Certificate of Survey - unrecorded - Larry L. Cavanagh,
P.S.#17614 - Set 1/2"x18" CIR#17614.
10" Oak S16°W 22.29'
10" Oak N75°W 27.20'
10" J. Pine N03°E 34.31'
6" Oak N88°E 18.20'

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

H-10 - C 1/4 Corner, section 27, T22N,R3W R3W

9 - CE 1/16 Corner, Section 27, T22N,R3W

Found 1/2"CIR#17614 per 1994 cert. of survey by Cavanagh. Iron is within 1.09' of calculated center position. Corner falls in a N-S & W barb wire fence lines. Accepted found 1/2" CIR as the best available evidence for the position of the corner. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls 54' East of a NW-SE trail road. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-10 - C 1/4 Corner, section 27, T22N,R3W R3W

9 - CE 1/16 Corner, Section 27, T22N,R3W

1/2"x18" CIR#17614

2" dia. Aluminum cap on 5/8"x34" rebar

Wit: N27°E 26.95' to set N&T on NW side 10" J. Pine
S47°E 43.83' to set N&T on SW side 8" J. Pine
S55°W 6.43' to set N&T on SE side 7" J. Pine
N40°W 36.24' to set N&T on SW side 9" Oak
Set Blue Carsonite post w/location tag 1' North

Wit: N23°E 29.72' to set N&T on W side 15" Oak
S69°E 2.01' to set N&T on N side 6" W. Pine
S19°W 34.12' to set N&T on SE side 9" R. Pine
N39°W 25.28' to set N&T on SW side 12" W. Pine
Set Blue Carsonite post w/location tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981



H-12-10