SURVEY & REMONUMENTATION

8333

APR 2 4 1995

ROSCOMMON COUNTY REMONUMENTATION TO BE FILED IN LIBER 3 OF LAND

LAND CORNER RECORDATION CERTIFICATE

COMMISSIORIING Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN ROSCOMMON COUNTY RECORDED

Fo	r corners in	South and the control of the control		RECOMPEN
_	Roscommon (County)	Located In:	Corner Code ##	14 NOV 94 3:04 P.H.
1.	Public Land Survey	T <u>22N</u> R <u>3</u> T R	<u>B-7</u>	ROBERT W. SMITH REGISTER OF DEEDS
		T R	1	ROSCOMMON COUNTY
2	Property Controlling	T R _ S T R _		PEER GROUP APPROVAL MEN
۷.	in Section	S T R:_		DATE
3.	Miscellaneous	S T R _		Register of Deeds Stamp & File Number
	Property in Sec.	S T R _		register of Deeds Stamp & The Humber
	d at Na	Departed Diet	· 	
				A B C D E F G H J K L M
O.	Tivate Otamio	· · · · · · · · · · · · · · · · · · ·		2 6 5 4 3 2
	•			3
		_		4 7 8 9 10 11 12
I, _	Larry L. Cavanagh	, in a field survey on $\frac{0}{2}$	ctober , 19 94	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 8 19 20 21 22 23 23				
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				
	or Law; established, pressed below:	re-established, monumente		10 30 29 28 27 26 25
	•	corners, all in the same t	own and range, may be recorded	11
	on this certificate			12 31 32 33 34 35 36
			• • •	13
A.			ies and/or subsequent restoration	
	Hemlock Post set by William Hemlock 22" N40°W 17 links		1976 survey by L. Cavanagh	LCRC Liber 1, Page 269
	Hemlock 20" S50W 17 links		Set 1/2" x 18" capped bar 5" Maple S45E 7.2'	(1989) same as 1976
	1101111011120		4" Oak \$40W 24.75'	,
	1948 survey of R.T. Ostling o	fN 1/2	(set according to plat of American	•
	of SE 1/4, Sec 18		Colony, proportional to GLO	·
	American Colony (plat) 1949	•	Survey)	
	Liber 3, Page 42	•	1982 survey by L. Cavanagh	
			Wit same as 1976	
	Description of severe		othed applied in rectaring or recel	tablishing corner
В.		evidence found and/or the	ethod applied in restoring or reest	ablishing corner.
	No original evidence found Found 1/2" bar as set in 1976			
	Found 5" Maple S45E (now 7)	")		
		,	·	·
			•	
		•		
				•
	_			
	•			
		•	•	
	•			
C.	Description of monum	ent for comer and access	sories established to perpetuate lo	ocating the position of the corner:
	M.A.160 A.W		•	
	Set 2 1/2" x 24" cast iron Rosc	common County Monument	·	

17614-1994 \$45°E nail and tag in 7" Maple 7.28 feet \$89°W nail and tag in 4" Maple 28.28 feet N13°W nail and tag in 5" Maple 27.03 feet N45°W nail and tag in 3" Oak 17.34 feet N80°E carsonite post 3.65 feet

Is accepted as the best available evidence of the position of the original corner.

Signed by

Surveyor's Michigan Licens

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976

MICHIGAN

LARRY L

CAVANAGH PROFESSIONAL SURVEYOR

No.

REVISED JAN., 1983

LIBER 3 PAGE 114