SURVEY & REMONUMENTATION

MAR 01 1999

STATE OF HICHIGAN

11509	LAND CORNER RECORDATION CERTIFICATE TON Filing Requirement of Act 74, Mich. P.A. 1970 F.	ILE	IN LIBER	3 OF	RDED LAND	CO
- comers in	a		22	DEC 70	2.4.	

RNERS

Corner Code # For comers in Located In: Roscommon (County) J-11 T 22NR 4W 1. Public Land Survey 2. Property Controlling


ROBERT W. SHITH REGISTER OF DEEDS

in Section 3. Miscellaneous

Register of Deeds Stamp & File Number

Property in Sec. _, Recorded Plat_ 4. Lot No. 5. Private Claims

1, Marvin E. Myers, in a field survey on November 24, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan bureau of Larid Management of by a decree of a Court of Law and for that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:



NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent LCRC L. 1, P 192 April 26, 1979

GLO - July 1852 John Brink, D.S. restoration:

Larry L. Cavanagh, P.S. #17614

Mon - 1/2" Bar

Mon - Post Wit: 16" Y. Pine N60°E 4 Lks 12" Y. Pine S25°W 19 Lks.

Wit: Fence Comer South 40.8 4" Poplar N70°E 50.24 3" Cherry N70°W 53.42

L. 263 P. 417 1972 L. L. Cavanagh PS # 17614 Mon - found 1/2" bar Wit: None given

1/2" Bar N0°20'W 33.0

April 1978 L. L. Cavanagh, P.S. #17614

Mon - 1/₂" bar

Mon - Not Given Wit: Fence Corner Post South 40.8

4" Poplar N70°E 50.24

3" Cherry N70°W 53.42

LCRC L. 2, P. 286

Wit: Fence Comer Post South 40.8

4" Poplar N70°E 50.24

3" Cherry N70°W 53.42

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: b. Description of corner evidence found and/or metriod applied in restoring of reestablishing corner.

Found ½" bar in fence N-S & W in line with centerline of Road East; found 3" (now 8") Cherry N70°W 53.42 Accepted ½"

The country of the best supplied of the position of the Odelan Country Restord to the best supplied of the position of the Odelan Country Restord to the best supplied of the position of the Odelan Country Restord to the Country Restord to round 1/2" par in tence in-5 & vv in line with centenine of hoad East; found 3" (now 8") Unerry in 10"vv 53.42 Accepted 1/2" bar as the best available evidence of the position of the Original Comer. Replaced bar with Standard Roscommon Count.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer. ROSCOMMON COUNTY

Mon - Standard Roscommon County Monument. Wit: Set PK nail & tag 8" Twin Black Cherry N75" 53.60

Set PK nail & tag 8" Poplar N21" 17.32

Set PK nail & tag 8" Twin Black Cherry S72°E 6.80

Set PK nail & tag 8" Twin Black Cherry S72°E 6.80

Set PK nail & tag Fence Post S11°E 33.89

Set Carsonite Post West 2.0

PEER GROUP APPROVAL DATE Dec 4, 1998

MANY E. OMMEN MONY

Marvin E. Myers, P.S. County Surveyor

SATE OF MICHIGAN MARVIN E. MYERS PROFESSIONAL SURVEYOR No. ¥31600 signed by

Date December 17, 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14.19: REVISED JAN., 19: REVISED OCT., 19: