

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
ROSCOMMON
(County)

Located In

Corner Code #

1. Public Land Survey		T	<u>22N</u>	R	<u>4W</u>	A-9
		T	<u>22N</u>	R	<u>4W</u>	B-9
2. Property Controlling in Section	S		T		R	
	S		T		R	
3. Miscellaneous Property in Section	S		T		R	
	S		T		R	

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on NOV. 17, 1998 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-9 GLO - JULY 1852 - ARTMUS CURTIS, D.S. SET POST.
28" WHITE PINE S51°W 28 LINKS
12" YELLOW PINE N54°W 46 LINKS

B-9 GLO - JULY 1852 - ARTMUS CURTIS, D.S.
SET QUARTER SECTION POST.
8" TAMARACK N51°E 13 LINKS
6" SPRUCE S87°W 6 LINKS

JACK ERICKSON, RLS # 16929 IN 1969 SET A 1/2" ROD AT A FOUND OAK STAKE.

MARCUS SHAAF, RLS #310 c.1940 SET AN 1-1/4" PIPE WITH CONCRETE BASE.

FRANK ARLETH, JULY 1979 FOUND 1/2" BAR
14" W. OAK N29°W 16.5'
8" W. OAK S53°W 26.0'
8" B. OAK N48°W 40.5'

FRANK ARLETH, PS #21266 JULY 1979 FOUND 1-1/2" PIPE
12" CEDAR S45°E 12.0'
12" TWIN MAPLE S85°E 20.9'
8" MAPLE N70°W 8.2'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

A-9 FOUND AND ACCEPTED A 1/2" ROD AS SET BY JACK ERICKSON, RLS#16929 FOR THE NW CORNER SECTION 30.

B-9 FOUND 1-1/4" PIPE WITH CONCRETE BASE AS SET BY MARCUS SHAAF, RLS #3104 FOR THE NORTH 1/4 CORNER OF SECTION 30.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 SET 1"X32" PIPE WITH ALUM. DNR MONUMENT CAP & CARSONITE POST.

B-9 SET 1"X72" PIPE WITH ALUM. DNR MONUMENT CAP & CARSONITE POST.

* 16" OAK N27°W 16.82'
* 16" OAK N52°E 40.62'
* 14&18" TWIN OAK S79°E 42.82'
10" OAK S57°W 26.47'
CARSONITE POST NORTH 1'
OLD FENCE CORNER WIRE N-S & E-W

* 8" MAPLE N55°W 8.35'
* 8" MAPLE S81°E 21.12'
* 12" CEDAR S27°E 12.74'
4" MAPLE S23°W 30.91'
EDGE OF LAKE EAST 42'
CARSONITE POST NORTH 1'

* OLD WITNESS BY OTHERS

* OLD WITNESS BY OTHERS

Signed by:

Carl T. Kiiskila

Date:

6-22-99

Surveyor's Michigan License No.:

33981

