SURVEY & REMONUMENTATION

2399

MAY 28 1997

COMMISSAND CORNER RECORDATION CERTIFICATE

	COMMISSION DAME CONTACT L		
For corners in	Filing Requireme	ent of Act 74, Mich. P.	
Roscommon	Located In:	Corner Code #	ROSCOMMON COUNTY Recorded
(County)			Wednier
			18 APR 96 10:03 A.M.
 Public Land Survey 	T <u>23N</u> R <u>2W</u>	<u>L - 9</u>	AN INC. THE APPROXITE
	T R		ROBERT W. SHITH
	T R		REGISTER OF DEEDS
	T R		
2. Property Controlling	S T R	<u></u> -	TO DE CILED IN LIDER 2 OF LAND CORNER
in Section	S T R		TO BE FILED IN LIBER 3 OF LAND CORNER
3. Miscellaneous	s T R		Register of Deeds Stamp & File Number
Property in Section	S T R		negister of beeds Staffip & File Number
	, Recorded Plat		A B C D E F G H I J K L M
5. Private Claims			
			4 - 7 - 8 - 9 - 10 - 11 - 12 - 1
1. Marvin E. Myers , in a field survey on April 10 , 19 96 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			
	of a Court of Law and/or that the corner		
5 above were in conforman	ce with the rules of the Michigan Board	of Professional Surveyors of	rby a
	stablished, re-established, monumented,	re-monumented, recovered,	found 10 30 29 28 27 26 25
as expressed below:			11
	corners, all in the same town and ran	ge, may be recorded	
on this certificate) .		12 31 32 33 34 34 35 36
A Description of origin	al monument and accessories and/	or subsequent restoration	n·
GLO-William Burt 1852			ROSCOMIMON COUNTY
Mon-Set Post Mon-Set at 39 75 chains Fact			
WIT: 9" B.Ash S83°E 11 1ks. PEER GROUP APPROVAL			PEER GROUP APPROVAL
12" Maple N78°W	33 lks.		DATE Am. 18 1996
			a con in
			Marin E. Myen Mills
			Marvin E. Myers, P.S.
			County Surveyor
B. Description of come	r evidence found and/or method ap	plied in restoring or rees	tablishing corner:
Henning survey 1946 w	sed to reestablish position.	ound post and lath S	outh and West placed by non-licensed
surveyor according to	local property owners.		
A reestablishment of	measure West 2587.90 feet to be the position of the original su	C-9 and East 2587.90 f	eet to M-9
n reestaurismment of	the position of the original so	iivey.	
			•
	<u>.</u>		
•			
C. Description of monu	ment for comer and accessories es	tablished to perpetuate I	ocating the position of the corner:
•	D x 54" pipe & cap "MEM 31600"	herberger	<u> </u>
WIT: Set carsonite po	st N15°W 13.60'		i e
Set nail & tag S	. side 4" Ash S84°W 74.33'	•	7
	S. side 14" Ash S57°W 74.93' WW side 11" Ash S13°W 77.12'		· · ·
Set nail & tag E	. side 5" Ash S45°E 69.59'		
•	•	.*	
			N
	_		A .
D.	- <i> </i>		2 = 1/ 1/ 222
Signed by Man	16 Meses	Date	HARX 11-9996
- /	21/02		
Surveyor's Michigan Lice	ense No. 31600	FORM	PPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
			REVISED JAN. 1983

LIBER 3 PAGE 291