

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon

(County)

Located In

Corner Code #

1. Public Land Survey

T _____ R _____
T _____ R _____

2. Property Controlling
in Section

S 3 T 23N R 3W 15
S 3 T 23N R 3W 12

3. Miscellaneous
Property in Section

S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 5, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4			3		2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

15- This corner position was not established during the original government survey.

12- This corner position was not established during the original government survey.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

15- Found 1/2 bar in a monument box. This corner fits proper subdivision of a section per standard B.L.M. instructions.

12- Found 1/2" bar as shown on North Central Survey Inc. October 2001 certificate of survey. This corner fits proper subdivision of a section as per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15- Found 1/2" bar in monument box

Wit: 3" Oak N06°E 27.64'
5" Elm N46°E 36.61'
7" White Pine S21°E 28.83'
10" Elm S32°W 33.57'

12- Found 1/2" bar

Wit: 8" Oak N45°E 30.47'
12" Oak S27°E 39.97'
8" Triple Oak N20°W 37.78'
7" Maple S24°W 64.67'
Carsonite Post West 33'±

Signed by:

Carl T. Kiiskila

Date:

7-22-02

Surveyor's Michigan License No.:

33981

