LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

Located In:

For corners in

Roscommon (County)

1. Public Land Survey	
2. Property Controlling S TR	
in Section S T R	
3. Miscellaneous S T R	,
Property in Sec. S T R	
	Register of Deeds Stamp & File Num
4. Lot No. , Recorded Plat	A B C D E F G H I J K L M
	2 6 5 1 3 2 1 1
5. Private Claims	
	4 7 - 8 9 10 11 12-1
	5
I, Craig W. McVean , in a field survey on Dec. 3 19 97 do	6 -18 -17 -16 -15 -14 -13
hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner	7
points mentioned in lines 1 and 2 above were in conformance with regulations and	8 19 20 21 22 23 24
rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a	9
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were	10 30 29 28 27 26 25
in conformance with the rules of the Michigan Board of Land Surveyors or by a	
Decree of a Court of Law; established, re-established, monumented, recovered,	11
found as expressed below:	12-31-32-33-34-35-36-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this	13
certificate.	
Certificate.	
A. Description of original monument and accessories and/or subsequent restoration:	
At Description of original monators and account account and account and account and account and account and account and account account and account and account account and account account and account account and account account account and account account account and account account account account account account account account account and account accoun	
 1914 Beuthien Survey in Section 1, T22N, R5W; W. Pine 10"-S6° W-20L., Pine 10"-S77°W-245L., W.Pine 10"-N29°E- Miss. Co. Bk. 20, P. 38-43 - M-55 Hwy. survey - Show Cor. & Distances E & W - 1919 Miss. Co. Bk 21. P.32-Dist. N. to A11 - No Date 1954 Robert Ostling - FND. Metal Mon. at CL. of M-55 1958 MDOT Survey M-55, Proj. F388(2); Boat Spike in 1" Pipe, N16°W-105.61'-End Fence Post, N42°E-89.86'-8" Poplar, S5°E-61.65'-end gate post. Missaukee Co. Remon. LCRC L.300, P.610 - J. Dean Geers - 1995 - FND. Iron in Mon. Box at Centerline of Road intersection. Set 2 1/2" brass Missaukee County Mon. on existing Iron in mon. box. S20°E - 58.51 - Set Iron S30°W = 68.44-4" Poplar S55°W - 84.52 - 10" Poplar N20°E - 94.58 - Top Center conc. R/W Post B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 	
A-1 & A-13 - Section Corner Common to Section 36,T23N, R5W, Section 31, T23N, R4W, Section 6, T22N, R4W and Section 1, T22N, R5W FND 2 1/2" Miss. Co. Brass Cap in Mon. Box per Remon. LCRC in CL. of M-55 & Co. Rd. 300 intersection. Monument accepted as the best available evidence of the position of the original corner.	
C. Description of monument for corner and accessories established to perpetuate locating th	e position of the corner:
A-1 & A-13 - 2 1/2" Missaukee Co. Brass Cap in Mon. Box S25°E 58.51' to FND. 1/2" Iron - Set Blue Carsonite Post along side (JDG) N22°E 94.47' to Hole in Top Center Conc. Proj. Marker (JDG)	LITE OF MICHIGA
S28°W 151.91' to N&T in E. Side 20" R. Pine scribed 'XBT' S10°E 163.33 to N&T in W. Side 8" W. Pine scribed 'XBT'	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No.
Ω	39088
Signed by Craix W. Ma Vear	Date
Signed by Nue // . // Weller	Date OFFSSION
Surveyor's Michigan License No. 39088	14/12/1997