

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Roscommon

Located In

Corner Code #

(County)

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	4	T	24N	R 01W 12
	S	4	T	24N	R 01W 13

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 11, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

12 - CS 1/16 corner, section 4, T24N, R01W

13 - SE 1/16 corner, section 4, T24N, R01W

1973 - Certificate of Survey - L.278, p.94&95 - George D. Henning, P.S. #2240. Set 1/2" bar and stake.
8" Maple S45°E 58.9'; 6" Poplar N51°E 20.8'

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12 - CS 1/16 corner, section 4, T24N, R01W

13 - SE 1/16 corner, section 4, T24N, R01W

Found 1/2" bar per Certificate of Survey - L.278, p.94&95 by Henning at fence corner North and West. Accepted found 1/2" bar as the best available evidence for the position of the corner. Drove 2" dia. stamped aluminum cap on 5/8"x34" rebar over found 1/2" bar. Corner fits the standard BLM procedure for subdivision of a section.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls 2.5' east of N-S barbwire fence remains. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12 - CS 1/16 corner, section 4, T24N, R01W

13 - SE 1/16 corner, section 4, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x34" rebar over 1/2" bar

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: N55°E 1.65' to set N&T on S side 10" W. Pine
*S44°E 59.22' to set N&T on NE side 10" S. Maple
S20°W 4.00' to set N&T on NW side 5" W. Pine
N72°W 15.43' to set N&T on N side 3" W. Pine
Set Blue Carsonite Post w/ loc. tag 1' South

Wit: N34°E 87.60' to set N&T on NW side 12" Cherry
S31°E 21.53' to set N&T on SW side 7" Cherry
S51°W 58.72' to set N&T on W side 20" Twin Ash
N67°W 37.12' to set N&T on S side 10" W. Pine
Set Blue Carsonite Post w/ loc. tag 1' North

* Witness of previous record.

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

6-1-11

