

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Roscommon Located In Corner Code #  
(County)

1. Public Land Survey	T	R	
	T	R	
2. Property Controlling in Section	S	T	R
	S	T	R
3. Miscellaneous Property in Section	S 9	T 24N	R 01W 3
	S 9	T 24N	R 01W 5

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:  
5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 28, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - N 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W  
None  
5 - CN 1/16 corner, section 9, T24N, R01W  
None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

3 - N 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W  
Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure flush w/ surface of N-S paved road. Corner falls 0.75' west of N-S centerline. Position fits well with occupation both E&W. Found no other evidence to dispute the location for the corner.  
5 - CN 1/16 corner, section 9, T24N, R01W  
Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found 1/2" bar N36°E 4.56' from calculated position that was set by Frank J. Arleth, P.S.#21266 per certificate of survey, L.288, p.106 in 1974 that was not accepted. Fence corner for fence running north and west is 16' north and 9' east of calculated position. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - N 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W  
2" dia. stamped aluminum cap on 5/8"x34"  
Wit: N70°E 53.40' to set PK&T on N side P. Pole  
S59°E 106.86' to set N&T on SW side 34" S. Maple  
S51°W 41.53' to 3" dia. metal fence post  
S85°W 30.33' to set PK&T on N side P.Pole  
Set Blue Carsonite Post w/ loc. tag 33' East  
5 - CN 1/16 corner, section 9, T24N, R01W  
2" dia. stamped aluminum cap on 5/8"x34" rebar  
Wit: N58°E 30.26' to set N&T on NW side 4" B. Fir  
S40°E 34.08' to set N&T on NE side 4" B. Fir  
S10°W 21.36' to set N&T on NW side 5" B. Fir  
N50°W 23.78' to set N&T on NE side 4" R. Maple  
Set Blue Carsonite Post w/ loc. tag 1' NE

Carl T. Kiiskila  
Surveyor's Michigan License No.: 33981

6-1-11

