

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Roscommon (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S 9 T 24N R 01W 10	_____
	S 9 T 24N R 01W 11	_____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on December 28, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

10 - S 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W 11 - SW 1/16 corner, section 9, T24N, R01W

None None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

10 - S 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W 11 - SW 1/16 corner, section 9, T24N, R01W

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure flush w/ surface of N-S paved road. Corner falls 7.5' west of N-S centerline. Corner falls 2' north of fence line west. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

10 - S 1/16 corner, comm. to sec.'s 8 & 9, T24N, R01W 11 - SW 1/16 corner, section 9, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x34" 2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: N50°E 75.60' to set N&T on NW side 10" B. Fir
S62°E 72.85' to set N&T on SW side 6" B. Fir
S57°W 38.40' to set PK&T on S side P. Pole
N45°W 79.33' to set N&T on SW side 8" B. Fir
Set Blue Carsonite Post w/ loc. tag 40' East

Wit: N83°E 28.72' to set N&T on S side 6" B. Fir
S08°W 10.38' to set N&T on W side 18" R. Maple
N56°W 22.09' to set N&T on N side 6" B. Fir
N01°E 19.70' to set N&T on E side 5" B. Fir
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila
Surveyor's Michigan License No.: 33981

6-1-11

