

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon
(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S	T	R	
	S	T	R	
3. Miscellaneous Property in Section	S 9	T 24N	R 01W	15
	S 9	T 24N	R 01W	16

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 28, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

15- W 1/16 corner, comm. to sec.'s 9 & 16, T24N, R01W

None

16 - E 1/16 corner, comm. to sec.'s 9 & 16, T24N,R01W

1968 - Certificate of Survey - unrecorded - C. Eugene Ostling, P.S. #12026. Set 1/2" x18" bar.
16" Elm N69°57'E 74.8'; 12" Poplar S20°47'E 57.0'
12" Poplar N22°51'W 53.0'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

15- W 1/16 corner, comm. to sec.'s 9 & 16, T24N, R01W

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

16 - E 1/16 corner, comm. to sec.'s 9 & 16, T24N,R01W

Found 1/2" x 16" bar per Certificate of Survey by C. E. Ostling at intersection of fence lines west and south. Accepted found iron as the best available evidence for the position of the corner. Replaced found iron with 2" dia. stamped aluminum cap on 5/8"x 34" rebar. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15- W 1/16 corner, comm. to sec.'s 9 & 16, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x34"

Wit: N59°E 43.08' to set N& T on N side 6" Ash
S36°E 32.10' to set N&T on SW side 12" Ash
S20°W 25.27' to set N&T on W side 6" Ash
S49°W 20.76' to set N&T on SE side 10" Ash
Set Blue Carsonite Post w/ loc. tag 1' North

16 - E 1/16 corner, comm. to sec.'s 9 & 16, T24N,R01W

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: S08°E 43.67' to set N&T on E side 3" B. Fir
S50°W 13.75' to set N&T on SE side 12" B.Fir
N76°W 29.49' to set N&T on S side 4" B.Fir
N20°W 22.66' to set N&T on W side 12" B.Fir
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

6-1-11

