

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon
(County)

Located In

Corner Code #

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S		T		R
	S		T		R
3. Miscellaneous Property in Section	S	16	T	24N	R 01W
	S	16	T	24N	R 01W
					4
					5

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 4, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

4- NW 1/16 corner, section 16, T24N, R01W

5- CN 1/16 corner, section 16, T24N, R01W

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

4- NW 1/16 corner, section 16, T24N, R01W

5- CN 1/16 corner, section 16, T24N, R01W

Set stamped 2" dia. aluminum cap on 5/8"x6' rebar per standard BLM procedure in marsh grass swamp. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x5' rebar per standard BLM procedure. Corner falls in E-W single strand fence. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4- NW 1/16 corner, section 16, T24N, R01W

5- CN 1/16 corner, section 16, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x6'

2" dia. stamped aluminum cap on 5/8"x5' rebar.

Wit: N50°E 74.90' to set N&T on N side 7" B. Ash
S36°E 22.69' to set N&T on NE side 5" B. Ash
N49°W 8.67' to set N&T on NW side 8" B. Ash
N13°W 112.20' to set N&T on E side 24" Crack Willow
Set Blue Carsonite Post w/ loc. tag 1' North

Wit: N88°E 21.80' to set N&T on N side 3" B. Fir
S50°E 26.90' to set N&T on SW side 4" B. Fir
S70°W 27.58' to set N&T on N side 9" B. Fir
N62°W 29.87' to set N&T on SW side 6" B. Fir
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

6-1-11

