

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Roscommon  
(County)

Located In

Corner Code #

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S		T		R
	S		T		R
3. Miscellaneous Property in Section	S	16	T	24N	R 01W 6
	S	16	T	24N	R 01W 7

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 5, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - NE 1/16 corner, section 16, T24N, R01W

Z - N 1/16 corner common to sec.'s 15 & 16, T24N, R01W

1968 - Certificate of Survey - unrecorded - C. Eugene Ostling, P.S. #12026. Set 1/2" x 18" bar. No witnesses.

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

6 - NE 1/16 corner, section 16, T24N, R01W

Z - N 1/16 corner common to sec.'s 15 & 16, T24N, R01W

Set stamped 2" dia. aluminum cap on 5/8"x5' rebar per standard BLM procedure. Corner falls S24°E 7' from leaning metal fence post with single strand wire running north and West. Found no evidence of Ostling's iron. Corner falls in tag alder swamp. No witnesses available. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls 23' south of E-W single strand fence and 10' West of N-S single strand fence. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - NE 1/16 corner, section 16, T24N, R01W

Z - N 1/16 corner common to sec.'s 15 & 16, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x5' rebar.

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: No witnesses available.  
Set Blue Carsonite Post w/ loc. tag 1' North

Wit: N30°E 26.50' to set N&T on NW side 7" B. Ash  
S60°E 11.15' to set N&T on S side 4" B. Fir  
S08°W 13.16' to set N&T on W side 10" Cedar  
N78°W 13.34' to set N&T on S side 10" Cedar  
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

6-1-11

