

# SURVEY & REMONUMENTATION

2026

OCT 05 1998

STATE OF MICHIGAN  
ROSCOMMON COUNTY  
RECORDED

## SECOND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

20 APR 98 2:19 P.M.

For corners in

Roscommon

(County)

Located in:

Corner Code #

ROBERT W. SMITH  
REGISTER OF DEEDS

1. Public Land Survey

T 24N R 1W

L-13

T 23N R 1W

L-1

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

To be filed in Liber 3 of Land  
Corners

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Marvin E. Myers, in a field survey on March 2, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

L-13 G.L.O. - 1838 Lewis Clason, DS  
Mon. - Post  
10" W. Pine N53°E 15 lbs.  
7" Spruce N65°W 22 lbs.

1900's Marcus Schaeff  
Michigan Dept. of Conservation  
Mon: Found or established, and replaced

L 2, Pg. 465  
Mon. - Axe Shaft in Center Line N-S Road  
5" Tamarack N66°W 93.7'  
6" Tamarack N22°E 90.4'

L 1, Pg. 101 (Herbert L. Fluharty,  
P.S. #18223 9-11-1974)  
Mon. - Found Gear Shaft in Center Line Co. Rd. 600  
P.P. N75°W 43.80'  
5" Poplar N50°E 50.69'  
9" Balsam N30°E 90.45'

L 1, Pg. 155 (Frank J. Arlath P.S. #2126  
April 2, 1975)  
Mon. - Found 1 1/4" Axe Shaft  
Nails in:  
P. Pole N80°W 43.8'  
6" Tamarack N30°E 90.5'

ROSCOMMON COUNTY  
PEER GROUP APPROVAL  
DATE MARCH 27 1998  
Marvin E. Myers M.E.M.  
Marvin E. Myers, P.S.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**  
Found 1 1/4" axe shaft in Monument box in the centerline of F97 (St. Helen Road) and 200± South of the centerline of Marl Lake Road  
Found spike in Southwest face Power Pole N72°W 43.90'  
No other accessories were found. Accepted as the best available evidence of the position of the Original Corner.  
Replaced 1 1/4" x 36" axe shaft with standard Roscommon County monument in monument box in centerline of F-97.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - Standard Roscommon County Monument in monument box.

Wit: Set carsonite post 33' East.

Found spike in Southwest face Power Pole N72°W 43.90'  
Set nail & tag in Southeast face 8" Poplar N52°E 50.43'  
Face of highway R.O.W. marker S50°E 41.49'  
Set nail & tag in Southwest face 10" Tamarack S19°E 101.45'

Signed by Marvin E. Myers

Surveyor's Michigan License No. 31600

Date April 10, 1998



LIBER 3 PAGE 499