LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		•			
Roscommon	Located In:	Corner Code ##			
1. Public Land Survey					
	T R				
	<u>T</u> <u>R</u>				
	T R				
2. Property Controlling	g S 34_ T 24N R 2W	_11*			
in Section	S_34 . T . 24N. R 2W .	9			

3. Miscellaneous

Property in Sec.


Register of Deeds Stamp & File Number

4.	Lot No.	, Recorded	Plat	 	
5.	Private Claims			 . —	

t, Carl R. Johnson., in a field survey on ____Feb. 19, ____, 19 __86__, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 11 Set by standard survey procedure for subdivision of a section.
 - 9 Set by standard survey procedure for subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" bar w/cap & cedar post 5" Red Oak S31°W 11.1' 14" Maple N61°E 15.1'

Set 5/8" bar w/cap & cedar post 4" Red Pine S74°W 11.2' 10" Red Oak S21°E 23.2'

CARL R.

JOHNSON
LAND
SURVEYOR
No.
30083

Signed by

Surveyor's Michigan License No. ___

30083

_ Date ___

NEVISED MAY 14, 1875