

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon
(County)

Located In

Corner Code #

1. Public Land Survey T T R
2. Property Controlling in Section S 9 T 24N R 04W 3
S 9 T 24N R 04W 12
3. Miscellaneous Property in Section S S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 28, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - N 1/16 Corner comm. to sec.'s 8&9, T24N,R4W

12 - CS 1/16 Corner section 9, T24N,R4W

1940's - Corner Index - Marcus Schaaf, P.S.#3104 - Index shows iron set. No witnesses.

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

3 - N 1/16 Corner comm. to sec.'s 8&9, T24N,R4W

12 - CS 1/16 Corner section 9, T24N,R4W

Found 1 1/4" pipe 1.5' above ground per M. Schaaf's index. Pipe did not fit the standard BLM procedure for subdivision of a section and was not accepted for this survey. Set 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure.

Set 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - N 1/16 Corner comm. to sec.'s 8&9, T24N,R4W

12 - CS 1/16 Corner section 9, T24N,R4W

Stamped 2" dia. alum. cap on 5/8"x34" rebar

Stamped 2" dia. alum. cap on 5/8"x34" rebar

Witnesses:

N59°E 1.95' to set N&T on NW side 8" Oak
S61°E 35.32' to set N&T on SW side 7" R. Maple
S31°E 6.44' to found 1 1/4" Pipe
S64°W 9.15' to set N&T on NW side 3" Sugar Maple
S58°W 15.30' to set N&T on SW side 7" Balsam Fir
Set Blue Carsonite Post w/loc. tag 1' North

Witnesses:

N41°E 24.98' to set N&T on NW side 11" W. Pine
S65°E 14.45' to set N&T on SW side 15" W. Pine
S41°W 17.10' to set N&T on NW side 6" W. Pine
N53°W 18.94' to set N&T on N side 8" W. Pine
Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

6-28-12

Surveyor's Michigan License No.:

33981

