

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Roscommon  
(County)

Located In

Corner Code #

- Public Land Survey  
T 24N R 04W E-4  
T 24N R 04W F-3
- Property Controlling  
in Section  
S  
S
- Miscellaneous  
Property in Section  
S  
S T R
- Lot No: Recorded Plat:
- Private Claims:

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Carl T. Kiiskila, in a field survey on December 28, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

E-4 ¼ corner common to section 8&9, T24N,R4W

GLO 1852 Addison P. Brewer set quarter section post  
Wit. 5" Tamarack N74°E 63 lks  
5" Tamarack S72½°W 67 lks

2001 Roscommon Co. Remonumentation Liber 3, Page 729  
Marvin Myers PS#31600 set a standard County monument  
at found M. Schaaf pipe.

### Witnesses:

Set Nail & tag in S side 6" Tamarack N64°E 4.65'  
Set Nail & tag in N side 6" Tamarack S82°E 7.00'  
Set Nail & tag in N side 6" Tamarack S83°W 9.65'  
Set Carsonite Post North 2.2'±

F-3 ¼ corner common to section 4&9, T24N,R4W

GLO 1852 Addison P. Brewer set quarter section post  
Wit. 7" Tamarack N41°E 11 lks  
12" Tamarack S4°W 16 lks

2001 Roscommon Co. Remonumentation Liber 3, Page 732  
Marvin Myers PS#31600 set a standard County monument  
at found M. Schaaf pipe.

### Witnesses:

Set Nail & tag in side 8" Birch N80°W 17.50'  
Set Nail & tag in side 6" Maple N72°W 3.43'  
Set Nail & tag in side 12" Maple N15°E 21.97'  
Set Nail & tag in side 12" Maple S51°E 6.55'  
Set Carsonite Post East 1'±

## B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-4 ¼ corner common to section 8&9, T24N,R4W

Found a standard County monument fitting Marvin Myers's  
record witnesses, set new nail and tag above found nails.

F-3 ¼ corner common to section 4&9, T24N,R4W

Found a standard County monument fitting Marvin Myers's  
record witnesses, set new nail and tag above found nails.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4 ¼ corner common to section 8&9, T24N,R4W

Standard County monument

### Witnesses:

N51°E 4.67' to set N&T on SE side 9" Tamarack  
S89°E 7.04' to set N&T on N side 7" Tamarack  
S39°W 15.65' to set N&T on SE side 7" Tamarack  
S84°W 9.62' to set N&T on N side 7" Tamarack  
Found Carsonite Post North 2.2'

F-3 ¼ corner common to section 4&9, T24N,R4W

Standard County monument

### Witnesses:

N13°E 22.05' to fd N&T on N side 11" R. Maple  
S47°E 6.58' to fd N&T on N side 11 R. Maple  
S31°W 13.39' to set N&T on W side twin 2" & 6" R. Maple  
N44°W 11.68' to set N&T on N side 7" R. Maple  
Found Carsonite Post North 1'

Signed by: Carl T. Kiiskila  
Surveyor's Michigan License No.: 33981

Date: 6-28-12

