JAN 2 4 1995

CONTROL CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN ROSCOKNON COUNTY

For corners in	Fining Requirement of Act 14, Mich. P.A. 1970			KECOKDED		
Roscommon (County)	Located In:	Corner Code #	1	14 AUG 9:	5 3:49 P.M.	
Public Land Survey	T24N			ROBERT W. SMITH REGISTER OF DEEDS		
in Section S 3 . Miscellaneous S	T R R T R T R T R T R T R T R T R T R T	DNUMEN'	To be	filed in liber	r 3 of Land Corne	
4. Lot No, Record	led Plat	APR 0 5 19				
5. Private Claims			MOL	- A B C D E - 2 - 6 - 5	_F G H 1 J K L M	
Marvin E. Myers , in a f do hereby certify that under requirement in lines 1 and 2 above were in conformanual of survey instructions of the Management or by a decree of a Cout 5 above were in conformance with the Decree of a Court of Law; established as expressed below: NOTE: Not more than 4 corners, on this certificate.	ents of P.A. 74, Michigan F nance with regulations and he United States Depart int of Law and/or that the he rules of the Michigan in d, re-established, monument all in the same town ar	P.A. of 1970, the corner point rules therefore as required transport of the Interior, Burcomer points mentioned in Board of Professional Survented, re-monumented, recorder angle, may be recorded.	ats mentioned in the current eau of Land lines 3, 4 and eyors or by a overed, found	7 8 - 13 - 20 - 9 10 - 30 - 29 - 11	21	
A. Description of original monu		•				
LO-A.P. Brewer Oct. 1852 on-Set Post IT: 16" W.Pine N55°E 44 1ks. 16" Y.Pine S38°W 36 1ks.	Mon-3/4" I ARROWHEAD	ing Aug. 29, 1968 Pipe HILLS L.6, pg. 41	L.288, pg.2 Mon-Unknowr WIT: None (

R.T. Ostling Oct. 15, 1946 Mon-2" Iron Pipe

MDOT Lyle Schalgried Sept. 3, 1958 Mon-Fd. ½" Gas Pipe WIT: 11" Oak N41°W 30.80' 11" Oak S69°W 26.87' 20" T.Oak N62°E 27.15'

ng Sept. 4, 1969 Mon-3/4" Pipe

L.2, pg.554 Mon-Unknown

WIT: Cor. is 653.871
East of NB C

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" x 47" Pipe with 6" x 12" x 12" square concrete (possible Marcus Schaff DNR, Surveyor, monument). Replaced with standard Roscommon County Monuemnt. Section subdivision by G.D. Henning compares reasonably well with current retracement survey. See Book 16, T24N, R4W County Records.

ROSCOMMON COUNTY PEER GROUP APPROVAL

Marvin E. Myers, P.S. **County Surveyor**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-Std. Roscommon County Monument
WIT: Fd. Spike in West face 8" W.Oak S30°E 10.61'
Fd. Spike 12" W.Oak N41°W 30.80'
Fd. Spike 16" Tw.R.Oak N62°E 27.15'
Fd. Spike North face 4" Norway S88°W 43.32'
Carsonite Post North 1.0'±

OF MICHIGAN MARVIN E. MYERS PROFESSIONAL

Date_

Surveyor's Michigan License No. 31600 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983