

SAGINAW COUNTY RE-MON 1997
LAND CORNER RECORDATION CERTIFICATE RECORDED & FILED
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **Taymouth Township**

#	Saginaw (County)	Located In:	Corner Code
1. Public Land Survey		T 10N R 5E	K-13
		T R	
		T R	
		T R	
2. Property Controlling in Section	S	T R	
	S	T R	
3. Miscellaneous Property in Sec.	S	T R	
	S	T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Ronald C. Prevost, in a field survey on 5-6, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-13 Post set by J. Wampler about 1822.
Beech 9" N.71°E. 36 L
Beech 9" S.74°W. 12L
County Surveyor H. Cary 1879, point not identified.
L.C.R.C. L1 P79 Leach, 1971, set t-iron & cap.
L.C.R.C. L5 P65 Rowe, 1980 re-set from wit's, point not identified.
Spicer Eng. notes of 1974, 1nd large pt'd stone 1.0' below gravel, set 3/4" iron bar beside stone.
Stone is 3.6' S & 1.3'W of Leach t-iron, 1974.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-13 Found 1/2" rod at approximate location of Leach t-iron, also found large pointed stone & 3/4" iron bar beside from Spicer notes of 1974.
Peer Group approved large pointed stone location 6-26-97.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13 Removed large pointed stone, nothing under.
Set 5/8" re-rod, Sag. Co. re-mon cap & mon box in place of stone 6-30-97.
N.50°E. 124.00 SW cor. house.
N.05°E. 4.06 1/2" rod.
N.10°W. 42.28 E. edge leg stop sign.
N.45°E. 49.83 nail & cap S. side corner post split rail fence.
East 132.65 2" pipe (K-1 T.9N.-R.5 E.)

Signed by

Ronald C. Prevost
Ronald C. Prevost

Date

9-25-97

Surveyor's Michigan License No. 24612

SEP 25 3 23 PM '97

MILDRED M. DODAK
REGISTER OF DEEDS
SAGINAW COUNTY MICH.

LIBER 2027 PAGE 84

Liber 7 Page 124
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**SURVEY &
REMONUMENTATION**

MAR 18 1998

SECTION

**APPROVED BY PEER GROUP
P.A. 345 OF 1990
SAGINAW COUNTY**

6-26-97 *[Signature]*

