LAND CORNER RECORDATION CERTIFICATERECORDED/FILED Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	SAGINAW COUNTY RE	MONUMENTATION	ייים מכט או די זי אל	
	SAGINAW	Located in: B'RUN TWP.	Corner Code #	1997 SEP 26 P 3: 26	
	(County)	•		MILDRED M. DODAK REGISTER OF DEEDS	
7.	Public Land Survey	T <u>10N</u> R 6E	M-5	SAGINAY COUNTY, MI.	
2.	Property Controlling	TR STR		EIBER 2027 PAGE 455	
	in Section	STR			
3.	Miscellaneous	STR	·····		
	Property in Sec.	S_T_R		Di Danauk	
			•	Liber , Vage 146	
				Register of Deeds Stamp & File Number	
4.	Lot No, R	Recorded Plat		regional of Decede Camp & File Rember	
				A B C D E F G H I J K L	
				2 - 6 5 4 3 2 1 -	
				3	
1. E	RIAN D FERGUSON in a	a field survey on	10 07 do horoby state that .	4 7 - 1 1 - 12 - 12 - 12 - 12 - 12 - 12 -	
1. BRIAN D FERGUSON, in a field survey on JUNE 17, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law					
and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the 7					
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, a 10 20 21 22 23 24 monumented, recovered, found as expressed below:					
		·		9	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 30 - 20 - 20 - 20 - 27 - 20				10 30 29 28 27 28 25	
	on this certificate	,		11	
				12 - 32 - 33 - 34 - 35 - 36 -	
				13	
A.	Description of original r	monument and accessories and/o	or subsequent restoration:		
	M.F. WOOD DOST SE	ET BY WAMPLER IN 1822			
	M-3. WOOD FOST SE	ELDI WAMPLEKIN 1822	<i>i</i>	APPROVED BY PEER GROUP	
			•	P.A. 345 OF 1990	
				SAGINAW COUNTY	
		•		9-18-91BUT	
			•		
B.	B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:				
	M-5: FOUND "T" IRON IN MONUMENT BOX				
	LCRC RECORDED IN L 1 PG 218				
	SURVEY RECORDED IN L 1372 PG 537, L 1699 PG 1443, L 1766 PG 1512, L 1681 PG 406				
	CHECKED SCRC WITNESSES FROM 1995				
	ACCEPTED BY THE PEER REVIEW GROUP AS THE BEST				
	AVAILABLE EVIDENC	CE OF THE POSITION OF THE O	PRIGINAL CORNER		
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
	M-5: SET 5/8" ROD W	//3" BRASS CAP IN MONUMENT	Т ВОХ		
	S45E 66.28' W. FC			The state of the s	
		TH LEG OF SIGN POST		ELE OF MICHIE	
	N45W 45.25' 3/4" F	PIPE WICAP 33980		BRIAN D	
	S30W 37.20' FCE (OF STREET SIG		FERGUSUN # V	
		n ()		SUNVEYOR *	
		1.//		8 26454 S	
Sign	ed by () //	perguson	Date	SEMEMBER 25 AST	
Surv	eyor's Michigan License	NOVE 2 26454		Marea	
REMONUMENTATION					

MAR 1 8 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995