

APPROVED BY PEER GROUP

P.A. 345 OF 1990

SAGINAW COUNTY

7-23-97

For corners in: FRANKENMUTH TWP.

1997 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED/FILED

LIBER 2028 PAGE 439

1997 OCT -3 A 8: 28

MILDRED M. DODAK
REGISTER OF DEEDS
SAGINAW COUNTY, MI.

Lib 7 Page 184

Register of Deeds Stamp & File Number

SAGINAW Located In: Corner Code #
(County)

1. Public Land Survey T 11N R 06E M-7
T _____ R _____
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, JONATHAN M. FIELD, in a field survey on JULY 8 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1821 GLO; WAMPLER, D.S.; NOT SET; "BALANCE OF THIS MILE & SEC. 24 & 13 & PART OF 12 IN RESERVATION"
1839 GLO; MULLETT, D.S.; SET POST; ELM 14 S53W 8LKS., ELM 18 N10W 26LKS.
1981 LEACH, LS#7236; LCRC L.5, PG.148; FND 3/4" ROD RAISED W/ 1" PIPE; EAST 9.30' S. LEG OF ROAD SIGN, S30W
41.45' ST. SIGN, N10W 104.47' P.POLE, S65W 83.55' P.POLE, NORTH 188.50' T-IRON AT A-7 T11N-R7E
1989 R/C ENG.; FERGUSON, LS#26454; SURVEY L.1891, PG.70; 1" PIPE W/CAP; SAME WITS AS 1981 LEACH SURVEY

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 ROWE; FIELD, PS#37276; FND. 1" PIPE W/CAP IN MON. BOX 3' E. OF C/L REESE ROAD & ON C/L ROEDEL ROAD TO
W.; RECOVERED 3 PREVIOUS WITNESSES WHICH INDICATE THAT FND. PIPE IS IN SAME POSITION AS 1981
LEACH LCRC CITED IN SECTION A. ABOVE

ACCEPTED FND. PIPE AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-7 SET 5/8" ROD W/ STD. REMON. CAP INSIDE FND. 1" PIPE IN MON. BOX
NORTH, 188.58' T-IRON
N84°E, 9.09' S. EDGE OF S. SIGN POST LEG
S37°E, 39.71' P-K NAIL W/TAG #37276 IN SW FACE P.POLE
S69°W, 83.66' P-K NAIL W/TAG #37276 IN SE FACE P.POLE
S53°W, 34.34' ROAD SIGN POST



Signed by Jonathan M. Field Date 9-25-97
Surveyor's Michigan License No. 37276

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 25, 1991

SURVEY &
REMONUMENTATION

MAR 18 1998

SECTION

REVISED MAY 14, 1991
REVISED JAN., 1991
ADAPTED FOR WORD PROCESSING MARCH, 1991