SAGINAW COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

		Filing Require	ement of Act 74, Mich.	. P.A. 1970	REGO	RDED & FI	-ED	
For corners	s in ginaw			•				
	(County)	Located In:	Corner Code ##		η ο	4 50		
	(OCDIN),				UEC 3	4 27 Ph	ł . 83	
1. Public	Land Survey	T <u>12 N.</u> R <u>4 E</u> .	D-3		bolt (s)			
		T R			RESIS	E. LOD.	AN TRO	
		T R		1	SACINAL	COUNTY	11CH	
		T R						4
	ty Controlling	S T R		1 1/	0.1	(y)	sell	18
in Sec				Su	w c	- //	,	
3. Miscel		\$ T R		Reg	ister of De	eds Stamp (k File Nu	mber
Proper	ty in Sec.	S R						
4 Lot No		Recorded Plat				D C E /	5 H I	
					A B C	D E F	<u> </u>	<u> </u>
		· · · · · · · · · · · · · · · · · · ·			2 6	- 5-+41	3 	2-1-1-
					3	╼╪╼┼╌┤		
					4 - 7 -	- b-+- b	-10	11
, Ronald C. Prevost , in a field survey on Oct./Dec. , 19 93 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					5		-+-+-	╅┈╂┈╂
do hereby c	ertify that under red	quirements of P.A. 74, Michigan P.A. n conformance with regulations and	of 1970, the comer points me dirules therefore as require	entioned ed in the	6 18	_1,71,6	15	14
current man	nual of survey instr	uctions of the United States Depart	ment of the Interior, Bureau	of Land	7			
/lanagemer	nt or by a decree of	a Court of Law and/or that the corne	r points mentioned in lines 3	3, 4 and 5	8 19	-2021		23
above were	in conformance wi	th the rules of the Michigan Board o	f Land Surveyors or by a De	cree of a	9			1-1-1
Court of Lexpressed (re-established, monumented, re-n	nonumented, recovered, 10	ouna as	1030	_2928	27	2625-
		11		and .	11		ïl_	
		corners, all in the same town an	ig range, may be record	ea	12 31			3536
00	n this certificate.	•			13	32 7 35	34	35-7-36
A. Descr	iotion of original	monument and accessories and	d/or subsequent restorat	ion:	13			
D-3 B. Descri	38.83 CHS W. to: 3/4" Pipe Set by S S.10.0 to Centerlir SW 67.0 Face P. NW 50.4 Face 15 SE 37.87 Face Te iption of corner e Found P.K. Na original corner	Pole * Hickory dephone Pole evidence found and/or method a dil (from recorded survey L 176	applied in restoring or restance of the following the foll	D-3 S D-3 S.C D-3 I	S.30°E. S.C.R.C. Witness Rec'd Surveys (All indicate s corner: st available	65.2 Spike N 61.5 Spike N esses, 1976, 3 ses, 1992, P.K : L 1578 Pg 21 L 1542 Pg 25 L 1761 Pg 76 ame position a	Base P. F. /4" Pipe Nail 122, L 1340 L 1599 F R L 1773 F R Recordin	Pg 622, gg 327, gg 1951 g L 1, Pg 4
C. Descri	Set 5/8" x 18" Ctr. Chain Lin Nail & Cap in Nail & Cap in Ctr. Hydrant S	Re-bar with Saginaw Co. Re-Nak Fence Post at SE Cor. Pump. W. Face P. & T. Pole S.25°E. E. Face P. & T. Pole S.20°W. S.45°W.	Aon Bronze Cap Stampe o Sta. N.20°E.			OX. STATE PROPERTY.	OF MIC.	NAL NAL
						PO	ESSION	AL

Surveyor's Michigan License No. _

24612

Date_