

LAND CORNER RECORDATION CERTIFICATE

1993 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

COMMISSION

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>12</u> N. S., R. <u>4</u> E. W.		G-12
2. PROPERTY CONTROLLING IN SECTION_____, T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION_____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

RECORDED & FILED
Liber 6 Page 189
Dec 22 2 14 PM '93
REGISTER OF DEEDS
SAGINAW COUNTY MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, DUANE F. LEDY, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on SEPTEMBER, 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on SEPTEMBER, 1993, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Wood post set in 1822 by Wampler at 40.00 chains.
No records available of date or method of placement of existing monument at G-12.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found concrete nail in gutterline on South side of Michigan Avenue.
Existing corner referenced in 1917 City of Saginaw surveys, no witnesses.
Measurements agree with City of Saginaw Resurveys.
Corner ratified by Saginaw County Remonumentation Peer Group Review on October 7, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" Rod & Sag. Co. Remon. 3" Brass cap in Monument Box
N 15 E 99.29 SW corner House #2122
N 15 W 94.74 SE corner House #4008
East 19.75 Centerline Water Box
S 20 W 39.82 Nail & brass tag marked "PS 21575" in E. side 10" Maple
N 45 W 77.92 Nail & brass tag marked "PS 21575" in SW side U.P.

SIGNED BY Duane F. Ledy DATE Dec. 22, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO. 21575

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____