

REMONUMENTATION

NOV 21 1997

LIBER

2 PAGE 118

REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T10N R12E

A - 1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, John A Millettics, in a field survey on May 15, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A - 1

GLO Notes

Beech 10 S23E 34½

Beech 10 S27W 27

APPROVED PEER BOARD MEETING

Aug 18, 1997 JM

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A - 1

Found Monu Box - removed by Sanilac County Road Comm. during reconstruction of Road, REPLACED using Act 74 recorded Liber 1 Page 382

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 1

NW Corner Section 6 T10N-R12E

Moun Box with iron and cap

S45°E 50.50' to a nail in a Power Pole

S35°W 99.00' to a nail in a Power Pole

N20°W 16.85' to a nail in a Guard Rail Post

N05°E 20.90' to the West leg of a Road Sign

N70°W 76.78' to a Road Sign

S40°E 54.25' to a Road Sign

East 2829.72' to the N 1/4 Cor Section 6

Signed by

John A Millettics

Date

Aug 11, 97

Surveyor's Michigan License No. 25859

RECEIVED FOR RECORD

97 SEP -9 AM 8:56

LIBER NO. 2 PAGE NO. 118

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

