94	DEC	16	AM	Q:	1. 1	

94	DEC	16	AM	9:

Approved Peer Board Meeting

Dec. 16, 1994

REMONUMENTATION ( )	LAND COME	EN NECONDATION CENTIF	ICAIC	-			F117 ,				
For corners in NUMENTAL	Filing Require	Filing Requirement of Act 74, Mich. P.A. 1970			LIBER HO 2 PASE NO. 26  ESTHER LEE  REGISTER OF DEEDS  SANILAC CO., MICHIGAN						
SAEMBC 1995	Located In:	Corner Code ##		\$,	REGIS ANILA	TER O C CO.,	F DEE MICH	DS IGAN			
For corners in NUMER 1995 Sactified (County) PR 1 1995  1. Public Land Survey MMSS	T 10 NR 14 E T R T	K - 11	٠.								
• • •	T R T R T R				•				-		
	T R T R	ľ	Regis	ter of De	eds S	tamp	& File	Numl	ber	_	
4. Lot No, Record				A B	C D (	E F	G H	IJ	K L	_	
5. Fivale Claims			*	2 6	_ 5	-4-	  3 	- ½-	+-	_	
John A Milletics in a	. Sold oursey on AUS	16 94		4 7	_8_	-9-	10-	1-11-		2-	
t, John A Milletics, in a field survey on Aug 16, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				6 18	_17_	16 	15-	14		_ 3-	
current manual of survey instructions: Management or by a decree of a Cour above were in conformance with the	t of Law and/or that the corne rules of the Michigan Board o	er points mentioned in lines 3, 4 an of Land Surveyors or by a Decree	nd 5 of a	8 19	-20	21	22	23	-2	- 4- L	
Court of Law; established, re-esta expressed below:			1	030	_29_	28  28	27	26	2!	5-	
NOTE: Not more than 4 corner on this certificate.	s, all in the same town ar	nd range, may be recorded	1	2 31-	-32	33	34-	35	31	6-	

Description of original monument and accessories and/or subsequent restoration:

GLO Notes K - 11

B Ash 10 S84W 7, B Ash 24 N84E 26 Set Post Corner

74 Form NONE Act

Act 132 Form NONE

Unrecorded Surveys Dated 1-10-1980, Dated 8-26-88

MDOT Right of Way Book Page 55

Road Comm

NONE

Drain Comm

NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K - 11

SE Cor Section 26 T1 ON-R14E

Found Monu Box - Raised Monu Box during Resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K - 11

SE Cor Section 26 T10N-R14E

Found Monu Box

South 6.5' to centerline of Blacktop

S30°E 46.2' to a nail in a guard rail post

S50°W 74.0' to a nail in a Power Pole S30°W 84.0' to a nail in a Tele Pole

N45°W 63.4' to a nail in a Power Pole

N70°W90.65' to a Road Sign

Surveyor's Michigan License No. \_\_\_\_25859

\_\_ Date \_\_ Signed by

Dec 9, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Land Surveyor No. 25859