

JAN 19 2000

RECEIVED FOR RECORD

1999 REMONUMENTATION PROGRAM
 LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

99 NOV 30 AM 9:03

LIBER NO. 2 PAGE NO. 324
 MICHELE VANNORMAN
 REGISTER OF DEEDS
 SANILAC CO. MICHIGAN

For corners in SECTION

SANILAC

(County)

Located In:

Corner Code #

1. Public Land Survey

T 11 N R 14 E

A-6

2. Property Controlling in Section

S

T

R

3. Miscellaneous Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

I, John A. Millettics, in a field survey on Aug. 2, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-6 Sugar 18 S44W 3 1/2; Birch 6 N1 1/2W 30

Old Survey Liber - Distance shown on sectional work done by Ward

Act 132 - None

Unrecorded Survey - None

L.C.R.C. - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6

W 1/4 Corner Section 18, T11N-R14E

Found evidence of corner as site

Set Corner a recorded distance in Old Survey Liber

APPROVED PEER BOARD MEETING
 NOV 19, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6

W 1/4 Corner Section 18 T11N-R14E

1/2" Iron Bar in gravel Road Bed

North 2652.54 to NW Corner

South 2665.46 to SW Corner

West 38.50 to a nail in a Fence Post

S25°E 106.25 to a nail in a Power Pole

N80°W 35.60 to the NE Corner of a Bell Riser Box

N80°E 37.00 to a Stop Sign

Signed by

Date 10-24-99

Surveyor's Michigan License No. 25859

