JAN 1 9 2000

	DEED /	ø.,	×3 I	A	
	F	٠,	2 9	9 1	i II a li
2 7	=(	١.	3 3	1 4	13 00

## 1999 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

99 NOV 30 AM 9: 03

LIBER N	o a	_PAGE	OSCON
PHU	ritilt Vi	ANNOR	ΜΔΝ =
KŁO	SISTER	OF DEE	DS .
5AN	LAC CO	. MICH	BADE

SANILAC (County)	Located In: Corner Code #	LIBER NO. 2 PAGE NO. 330 MICHELE VANNORMAN REGISTER OF DEEDS SANILAC CO., MICHIGAN
Public Land Survey	T11NR 14E A-13 T R T R	
Property Controlling in Section     Miscellaneous Property in Sec.	S T R S T R S T R S T R	
4. Lot No, Reco	rded Plat	Register of Deeds Stamp & File Numbe

I, <u>John A. Milletics</u>, in a field survey on <u>Aug. 2</u>, 19 <u>99</u> do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

	A	В	С	D	E	F	G	н	т	т.	ĸ	T	ħ.
1	Γ-	Ť	Ť	Ť	Ť	İΤ	Ť	Ϊ	┪~	Ť	<del>`</del>	ᅷ┈	ľ
2	$\vdash$	6-	┼-	<u>\$</u> _	—	4	4	- 3	ļ	! 2	4_	1_	
3	<u> </u>	↓_	-	╽-	$\perp$	ļ	$\bot$	_		$\perp$	_	$\perp$	
4	$\vdash$	ļ 7—	-	8-	+	9	_	10-	<u> </u>	 1 <sub>.</sub> 1—	-	12-	
5	<u> </u>	├-	-	-	<del> </del>		<del></del>	┿	_	-	1	_	
6	<u> </u> -,	ا ا	-	ļ 1,7—	<del> </del> 1	ا ا6—	-	 15	1	 1 <sub>.</sub> 4~	_	 13	4
7	<u> </u>	<u> </u>	ļ	<u> </u>	<u> </u>	ļ	1		<u> </u>	L			
8	1	   	<u> </u>	] 20—	L.	 21—		 22 <u>—</u>	<u> </u>	 23_		 2 <b>4</b> —	
9	ļ		_	<u> </u>	<u> </u>	<u> </u>	L	1		_		Ĭ	
10	L_3	<b>0</b>	<u> </u> -:	ا 29—	-	 ≥8—	-	 27	L.	 26	<u> </u>	 25	
11			_	_	ļ	_	_	<u> </u>	$\vdash$			_	┦
12	3	1	<u> </u> -:	2	Щз	3	<u> </u>	] 3 <b>4</b>	1_3	  5—	ļ:	 36—	4
13			<u> </u>										ľ

A. Description of original monument and accessories and/or subsequent restoration:

A-13 Hemlock 9 S22W 12; DO 9 S57E 21

Old Survey Liber - None

Act 132 - None

5. Private Claims

L.C.R.C. Liber 2 Page 139

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-13

SW Corner Section 31, Tl1N-R14E Found Monu. Box with 1/" Fin in Place North 2653.78 feet to W 1/4 Corner East 2645.08 feet to the S 1/4 Corner West 2660.00 feet to the S 1/4 Corner Accepted as best evidence

APPE	ROVED	PEER	BOARD	MEETING
NOV	19,19	799		
•	-	m	1	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-13

SW Corner Section 31 Tl1N-R14E Monu Box with 1/2 pin in place N45°W 29.00 feet to the north end of a 42" CMP N30°E 54.00 feet to a Tele Phone Box

South 18.20 feet to the west leg of a Road Sign

North 2653.78 feet to the W 1/4 Corner

East 2645.08 feet to the S 1/4 Corner West 2660.00 feet to the S 1/4 Corner

Signed by Surveyor's Michigan License No. 25859

AN Se. St. Might Co.
The A. Man

Date <u>Nov 15, 1999</u>