

JAN 22 2001

LIBER

3 PAGE 29

RECEIVED FOR RECORD

SECTION

2000 Remonumentation Program
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV 27 AM 8:55

LIBER NO. 3 PAGE NO. 29
MICHELE VANHORN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac Located in: Corner Code #
(County)

1. Public Land Survey T11N R15E L - 7
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

2000

John A Millettics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes
Sugar Maple 8" N06°W 20Links
Elm 8" S12°W 25Links

Act 132 - None

L.C.R.C Forms - None

Unrecorded Surveys - Sanilac Land Survey Aug 1977, Sanilac Land Survey June 1978
Millettics Dec 1994

Old Survey Liber - None

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L - 7
S 1/4 Corner Section 13 T11N-R15E
Found 1/2" Iron in gravel road bed
West 2664.40 feet to the SW Corner Section 13
East 2664.14 feet to the SE Corner Section 13
Accepted as best evidence



2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L - 7
S 1/4 Corner Section 13 T11N-R15E
1/2" Iron in gravel road bed
N45°W 35.00 feet to a nail in a 18" Ash
N60°W 55.20 feet to a nail in a 18" Maple
North 33.00 feet to a 1/2" Iron Bar
N30°W 65.40 feet to a nail in a 18" Elm
West 2664.40 feet to the SW Corner Section 13
East 2664.14 feet to the SE Corner Section 13

APPROVED PEER BOARD
MEETING NOV 25 2000
gm

Signed by John A Millettics
Surveyor's Michigan License No. 25859

Date Nov 15, 2000