

JAN 19 2000

LIBER 2 PAGE 369

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

99 NOV 30 PM 1:16

For corners in

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T12N R12E	C-7
	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

LIBER NO. 2 PAGE NO. 369  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, John A Milletics, in a field survey on Nov 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C - 7

GLO NOTES - Set Post - B. Ash 14 N5E 13, Cedar 10 S44W 12

OLD SURVEY LIBER - Page 411 Oct 1911 Thomas Nicol

L.C.R.C. - Liber 1 Page 352

Act 132 - Liber 2 Page 254

Unrecorded survey - dated 1981 Kay Eng - dated 1979 Kay Eng - dated 1993 Milletics

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C - 7

SE Corner Section 18 T12N-R12E

Found 3/4" Iron bar in Monu Box

West 2608.20 feet to the S 1/4 Corner Section 18

East 11.70 feet to Centerline M-53 as called for in

MDOT Right of Way Book

Accepted as best evidence

APPROVED PEER BOARD MEETING  
NOV 19, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C - 7

SE Corner Section 18 T12N-R12E

3/4" Iron Bar in monu Box

West 2608.20 feet to the S 1/4 Corner Section 18

East 11.70 feet to the centerline M- 53

N75°E 77.50 feet to a nail in a Power Pole

N30°W 58.10 feet to the SE Corner of a Bell Riser Box

N45°W 51.35 feet to a R/W Marker

S20°W 43.00 to a nail in a Guard Rial Post

Signed by John A Milletics

Date Nov 11, 1999

Surveyor's Michigan License No. 25859