## **SURVEY &** REMONUMENTATION

APR 1 4 1998

REMONUMENTATION

2 PAGE 182

RECEIVED FOR RECORD


LAND CORNER RECORDATION CERTIFICATE

| 97 DEC -2    | AM 9:            | 11  |
|--------------|------------------|-----|
| LIBER NO 2 P | AGE NO           | 185 |
| REGISTER (   | R LEE<br>IF DEFO | e   |

| For corners in CUSTER T              |   | Requirement of Act 74, Mich. P.A. | LIDER NIL '2' BACE NA 171-4                              |
|--------------------------------------|---|-----------------------------------|--|
| Sanilac<br>(County)                  | Located In:                             | Corner Code #                     | ESTHER LEE<br>REGISTER OF DEEDS<br>SANILAC CO., MICHIGAN |
| 1. Public Land Survey                | T <u>12N</u> R <u>141</u><br>T R<br>T R | E E - 7                           | SURVEY & REMONUMENTATION                                 |
| Property Controlling in Section      | TR<br>S TR<br>S TP                      |                                   | JAN 0 8 1998   |
| 3. Miscellaneous<br>Property in Sec. | S TR<br>S TR                            |                                   | SECTION<br>Register of Deeds Stamp & File Number         |
| 4. Lot No, Reco                      | rded Plat                               | ***                               | A B C D E F G H I J K I.                                 |

John A Milletics, in a field survey on <u>July15</u>, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

E - 7 GLO Notes

> Set Post Corner Pine 9 S58°E 6 B. Ash 8 S70°W 9

Old Survey Liber, survey dated Dec 1896 by Ward, survey dated May 1902 by Nicol

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box with 5/8' Iron Bar

APPROVED PEER BOARD MEETING NOV. 26, 1997

| C.  | Description of monument for corner and accessories established to perpetuate E - 7                     |                                 |     |
|-----|--|---------------------------------|-----|
|     | NE Corner Section 20 T12N-R14E Custer Twp.   | William Co. W. C. C.            |     |
|     | Monu Box in place with 5/8" Iron Bar<br>N45°E 67.98 feet to a nail in a Power Pole                     |                                 |     |
|     | N45°W 74.10 feet to a nail in a Power Pole   | John A. Milletics Land Surveyor | -   |
|     | S45°W 74.90 feet to a nail in a Power Pole<br>S55°W 46.20 feet to a stop sign                          | No. 25859                       | *** |
|     | N55°E 39.90 feet to a stop sign  |                                 |     |
|     | South 2673.49 feet to the E 1/4 Corner Section 20<br>North 2675.64 feet to the E 1/4 Corner Section 17 | Missional Sullive               |     |
|     | 1075.64 feet to the E 1/4 Corner Section 1/  | www.                            |     |
| Sig | ned by SMH/With  | Date Nov 12, 1997               |     |
| Su  | rveyor's Michigan License No. 25859  |                                 |     |