

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

,	10 24508 NO. 24508 NO. 24508	LAND CORNE	R RECORDATION CE	RTIFICATE	- A - A - A - A - A - A - A - A - A - A		
		Filing Require	ment of Act 74, Mich		ALCHO S		
	FO LAND SO	i imig i ioquiio			RE S		
	-	Located in:	Corner Code ##		70 2		
		Burtchville Towns		·			
1.	Public Land Survey	T 8N R 17E	λ-1		11 - 젊의 씨 - 트립		
		T R	` _		29 - 15		
		T R	· · · · · · · · · · · · · · · · · · ·		일		
	<u>.</u>	<u>T</u> R			開 & 多		
2.		TR			γ ος ος 1		
		TR		i :			
3.	· · · · · · · · · · · · · · · · · · ·	TB		Register	of Deeds Stamp & File Number		
	Property in Sec. S _	T R		L			
4	Lot No, Recorde	d Plat	,				
	Private Claims	J. 121			BCDEFGHIJKEN		
				2	-6- 5432		
		•		3			
			•	4			
I	John C. Niederhauser in a f	ield survey onJuly 1	LO 19	96			
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as							
	pressed below:			10	-30 -29 -28 -27 -26 -25		
				11			
NC	TE: Not more than 1 corner,	may be recorded on this	certificate.	12	-313233343536		
				13 .	_		
A. Description of original monument and accessories and/or subsequent restoration: Joseph Wampler set a wood post in 1822 as the original government corner. It is a common corner to four (4) townships per the original field notes. Reference corners: M-1 of T8N-R16E, M-13 of T9N-R16E and A-13 of T9N-R17E. B. Collins, P.S. recovered and recorded an "iron" September, 1974, see LCRC Liber 2, Page 207. Subsequent surveyors recorded a "found iron bar" (L 14, Page 14 of Surveys), "found iron #19835" (L 12, Page 379 of Surveys) and "Found 1-1/2" pipe with 1/2" rerod inside" (L 8, Page 388 of Surveys). Old County Surveyors Record shows "post".							
κ.				•			
	·						
,				*			
B	Description of corner evidence	found and/or method ann	lied in restoring or reesta	hlishing corner			
٠.	Found 1/2" rerod with ob	•	•	· •	r line of N-S and E-W		
_	avel roads. Verified co	rner by occupation a	and distance east r				
		1			REMONUMENTATION		
				* (*)			
					JUL 1 4 1997		
			and the second of the second o		COMMISSION		

_	Description of manument for or	arner and accorpories act	oblished to perpetuate la	cation the position	of the corner		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2" diameter aluminum cap with magnet attached and inscribed "St. Clair County Official
Corner" on the existing 1/2" rerod. This corner marks the intersection of four (4) townships. For
additional information reference corners M-1 of T8N-R16E, M-13 of T9N-R16E and A-13 of T9N-R17E.

South 39° W 73.23 feet to set P.K. nail with county remon tag over spike in power pole.

South 38° E 46.42 feet to set P.K. nail with county remon tag over spike in fence post.

North 56° E 53.96 feet to set P.K. nail with county remon tag in top of wood post.

North 70° W 85.45 feet to set P.K. nail with county remon tag in south side twin 8" Elm.

West 2626.61 feet to found "T" iron on centerline Fisher Road at fence line north.

North 2622.72 feet to found 3/4" rerod on centerline State Road at fence line west.

PA 345-1990

PEER COMMITTEE

APPROVED 7-19-4(

UCH 2032.29 Teel to lound 3/8 Telod on centelline state wad at	p 6166 11	APPROVED 7-19-44
		Waniels Johnson
Signed by	_ Date _	July 18, 1996
Surveyor's Michigan License No. 24608	·	105. On8 107 276