

NOV 04 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ST. JOSEPH

(County)

PARK TWP.

1. Public Land Survey

Located In:

Corner Code #

T 5S R 11W

B-11

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

LIBER 5 PAGE 22

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

19 SEP 97 2:56 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, WAYNE A. MOSTROM, in a field survey on AUG. 8, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

1866 SURVEY IN A/146
STAKE, STONES & BRICK
FROM ORIG. BEARINGS

1936 SURVEY BY MURRAY
USE MARK AT C BLACKTOP
MARK IS ON LINE BET. STONE
AT NE COR. & FENCE TO W.
OF MARK

1961 SAYERS SURVEY
21" PINE=N35°W 67.85'
POLE=N75°E 67.85'
POST=WEST 32.66'
23" MAPLE=S45°W 42.1'
22" MAPLE=S35°E 47.77'

1983 LCRC IN 2/162
PIPE IN MON. BOX
26" PINE=N29°W 67.7
12" MAPLE=N71°E 66.
P.P.=S89°W 35.9'

1878 SURVEY IN A/29
CEDAR STAKE & STONES
FROM ORIG. BEARINGS

1937 SURVEY BY MURRAY
SQUARE IRON ROD IN C PAVEMENT

1925 SURVEY BY MINE
2"X6" BOILER FLUE
IN BRICK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" X 18" PIPE OVER 2" BOILER FLUE IN MON. BOX
IN C OF N-S RDWY. & IN C OF ROAD TO EAST
AND IN FENCELINE TO WEST
26" PINE = N29°W 67.7'
12" MAPLE = N71°E 66.85'
POLE = S89°W 35.9'
23" MAPLE STUMP = S45°W 42.1'

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON AUG. 11, 1997
Wayne CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8' X 24' BAR W/STD. CAP INSIDE FLUE IN MON. BOX
N & W IN SW SIDE 26" PINE=N29°W 67.75'
N & W IN N SIDE 26" MAPLE=N71°E 66.85'
N & W IN S SIDE TELE. POLE=S89°W 35.90'
N & W IN N SIDE P. POLE=S78°E 117.92'



Signed by Wayne A. Mostrom
Surveyor's Michigan License No. 14100

Date 9/17/97