## NOV 0 4 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

TREE 1 PAGE 17

roi comers in				l	TIDEK A	PROC 1			
ST. JOSEPH (County)	Located In:	Corner Co	ode#			STATE OF			
PARK TWP.						ST. JOSE		ſΥ	
1. Public Land Survey	<u>T_5S_</u> F	R <u>11W</u> <u>B∸</u> R	13			Г	TLED		
		<u> </u>	<del>"</del>			17 SEP 97	3:25 1	Р.Н.	
2. Dromonte Controllina	ŢF		······			CAMAN	a jarra	rT	
Property Controlling     in Section	S TF	<u> </u>					R OF DE		
3. Miscellaneous S TR									
Property in Sec.	S F	<u> </u>	<del></del>		Register	of Deeds	Stamp &	File N	umber
4. Lot No, Recor	rded Plat	····			АВС	DEF	G H	ΙJ	K L
3. Filvate Claim's					2 6	ŢŢŢ	ĪŢ	ŢŢ	ΪŢ
					3				
I, WAYNE A. MOSTROM, in a field survey on SEPT. 9, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in						_	10-	11-	12
conformance with regulations and	an P.A. of 1970, the cor I rules therefore as requi	ner points mentioned red in the current ma	t in lines 1 and 2 abo nual of survey instruc	ove were in tions of the	5	11-		1	1
United States Department of the I that the corner points mentioned	Interior, Bureau of Land I	Management or by a	decree of a Court of I	aw and /or	6 -18	-17-16-		1,4	1,3-
Board of Land Surveyors or by	a Decree of a Court	of Law; established	i, re-established, mo	e michigan numented,	7			<del>                                     </del>	+
recovered, found as expressed be		•			819	-2021	2'2	23_	24
NOTE: Not more than 2 corr on this certificate.	ners, all in the same tov	wn and range, may	be recorded		9		<del>   </del> -		
on and connected.					10 30	-2 <del>9 </del> 28- 	27	26-	25-
					11 12 31	32 33		35	36-
					13				
A. Description of original mo	nument and accesso	ries and/or subsec	quent restoration:		•				
EARLY MOOT DATA (NO	DATE)	1983 LCRC	IN 2/162	SAYE	RS OLD W	ITNESS E	100K (1	JO DA	JF)
1/2" PIPE DRIVEN IN		PIPE IN MON	N. BOX		MAPLE = 1				50'53
RR SPIKE FD. IN PAV' DUG UNDER SPIKE - FC	MT NOTHEN	P.P. = N41		2911 /	MAPLE = 1	√50°E 5	0.69		
25" MAPLE = \$87°E 3	38.31	P.P. = \$36° P.P. = \$59°	'W 55.91 'F 63.281		MAPLE = E . POLE =			1	
18" LOCUST = S54°W	66.61	1" IRON = E		1 L-L-L-	. FOLE =	N40 W	22.04		
					SAYERS	OLD NO	TES (N	10 DA	TE)
B. Description of corner evid	dence found and/or m	ethod applied in re	estoring or reestab	lishina corne	NW COF	R HSE =	NE 89.	.92†	
B. Description of corner evidence found and/or method applied in restoring or reestablishing FOUND 3/4" PIPE IN MON. BOX IN CENTERLINE RDWAY TO WEST AND					SW COR HSE = NE 75.88' SE COR HSE = NW 115.58'				
2.5 ' WEST OF CENTERLINE N-S RDWAY. (ON CURVE)						APLE = N			51
18" LOCUST = S54°W NW COR HOUSE - NE 8		_ 57691./ FF			29" M	NPLE = N	50°E	50.69	91
SW COR HOUSE = NE 7	'5.88' P.P.	= \$36°W 55 = \$59°E 63	5.28'		24'' M	APLE = E	AST 38	.461	
SE COR HOUSE = NW 11	5.581			RATIF	IED BY P	EED CDC	u n		
P.P. = N41°W 49.12' CORNER CHECKS WITH SHADY BROOK SUBDIVISION					CORDANC	E WITH F	P.A. 34!	3	
	THE BROOK SOL	10101010		YIY =	rept. E	5	1997	7	
					CO, R		ITATIV	<u> </u>	
C. Description of monument f						St. Sec.			
SET 5/8" X 24" BAR W CENTERLINE ASPHALT R	/STD CAP IN MO	ON. BOX			E OF	I/C			
CORNER IS IN CENTERL	INE ROADWAY TO	) WEST			C) At Osmoon	The state of the s	ė.		
FOUNDATION @ NW CORN	ER HOUSE = N56	S°E 89.901		<b>7</b> 3	/ WAYN	RON A			LIBER
FOUNDATION @ SW CORN	ER HOUSE = N84 ER HOUSE = NEC	1°E 75.881			PROFESS	SIONAL			
NAIL & WASH IN NE S	IDE TELEPHONE	POLE = N41°	W 49.01'	E CO	No.				<u></u>
		_	÷ • • •		P. 141	YOR CO	#		PAGE
/,	$\alpha/$	2			SURVE NO 141	1047			J
Signed by	V Charles		_	. c=	WAYN MOST PROFESS SURVE NO 1410	11 1	007		
Surveyor's Michigan License N	lo. 14100		Da	πe <u> </u>	. IEMDER	. 11, 1	997		