

SURVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 4 PAGE 282

For corners in

ST. JOSEPH
(County)

Located in:

Corner Code #

PARK TWP.

1. Public Land Survey

T 5S R 11W

K-12

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

10 DEC 96 2:27 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, DAVID W. MOSTROM, in a field survey on FEB. 22, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(K-12) $\frac{1}{4}$ CORNER BETWEEN SECTIONS 35 & 36 T5S, R11W

*1877 SURVEY IN BK.A, PG 226
STONE FROM ORIG. BRG'S STILL
STANDING

ANCHOR POST = EAST 29.17
TELE. POLE = S89°E 73.00'

16" OAK = WEST 47.90'
ANCHOR POST = EAST 29.4'

*1964 SAYERS SURVEY

+D STONE IN MON. BOX

*1973 KESTER SURVEY
SAME AS 1964 SAYERS SURVEY
*1974 SAYERS SURVEY

*1987 MOSTROM SURVEY

19" BLACK OAK = N89°W 49.35'

19" BURR OAK = N36°E 38.32'

+D STONE IN MON. BOX

3/4" PIPE IN MON. BOX

20" OAK = WEST 49.0'

ANCHOR POST = EAST 29.8'

10" OAK = SE 55.5'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K-12)

FOUND 3/4" PIPE OVER +D STONE IN MON. BOX

14" OAK = S40°E 55.5'

ANCHOR POST = EAST 29.8'

32" OAK = WEST 49.0'

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON SEPT. 9, 1996
W.G. CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-12) $\frac{1}{4}$ CORNER COMMON TO SECTIONS 35 & 36 T5S, R11W

SET 5/8" X 24" IRON BAR W/STD. REMON. CAP OVER STONE IN MON. BOX

N & W IN SW SIDE OF 14" OAK = S40°E 55.50'

N & W IN N. SIDE OF 6" ELM = N75°E 31.80'

N & W IN N. SIDE OF ANCHOR POST = EAST 29.80'

N & W IN S. SIDE OF 20" OAK = WEST 49.00'

CORNER FALLS 0.7' SOUTH OF PROJ. OF FENCE TO EAST



Signed by J. DW. NT DAVID W. MOSTROM

Date DECEMBER 2, 1996

Surveyor's Michigan License No. 32339

LIBER 4 PAGE 282

REMONUMENTATION